

DAILY DRILLING REPORT (SYNTHETIC)

OIL-DGB-010 - Digboi-010

NWIS prototype document - not an Oil India Limited operational record

Field / Formation	Digboi / Tipam
Report Timestamp	2015-08-22 18:00:00
Current Depth	2527.0 m
Mud System	Low-Solids WBM
Well Risk	Moderate (51.9/100)
Latest Alert	Normal

Recent Drilling Parameters

Timestamp	Depth	SPP	Torque	RPM	MW	Flow In/Out	ROP	State
08-17 20:02	2434	2934	215	114	11.15	770/777	7.9	Normal
08-18 09:09	2444	3096	247	107	11.08	770/796	9.4	Normal
08-18 22:15	2454	3078	248	110	11.01	766/760	8.1	Normal
08-19 11:21	2465	3087	237	114	11.15	747/758	10.7	Normal
08-20 00:28	2475	3098	257	115	11.25	748/732	14.9	Normal
08-20 13:34	2486	3069	216	119	11.32	836/826	13.0	Normal
08-21 02:40	2496	3149	223	100	11.37	793/810	9.4	Normal
08-21 15:47	2506	3153	264	107	11.30	751/747	8.5	Normal
08-22 04:53	2517	3038	250	113	11.29	755/740	3.9	Normal
08-22 18:00	2527	3112	247	96	11.27	734/734	7.7	Normal

Operational Events / Lessons

Torque Spike (Medium) at 1812 m: Torque Spike at 1812 m in Tipam. Torque rose without corresponding pressure anomaly. Adjusted rotary parameters and observed response. Outcome: Spike cleared with no equipment damage. Torque 267 kNm, drag 16.9 t, ROP 12.5 m/h. Recommended action: Reduce WOB/RPM proactively near correlated torque-spike depth

Kick (Medium) at 2130 m: Kick at 2130 m in Tipam. Unexpected background gas rise preceded influx. Stopped drilling and performed flow check. Outcome: Well stabilized after controlled circulation. Gas 193 units; pit change +6.5 bbl; mud weight 10.96 ppg. Recommended action: Raise kick advisory when flow-out exceeds flow-in with rising gas

Stuck Pipe (High) at 2277 m: Stuck Pipe at 2277 m in Tipam. Torque and drag increased while ROP declined. Reduced WOB and increased hole-cleaning circulation. Outcome: Pipe movement restored after circulation and working. Torque 303 kNm, drag 40.6 t, ROP 2.5 m/h. Recommended action: Plan preventive wiper trip near analogous interval

Kick (Medium) at 2413 m: Kick at 2413 m in Tipam. Flow-out exceeded flow-in and gas units increased. Circulated influx under controlled conditions. Outcome: Influx circulated out and overbalance restored. Gas 147 units; pit change +7.0 bbl; mud weight 11.14 ppg. Recommended action: Set flow-check trigger for unexplained pit gain

This DDR is generated from synthetic telemetry for OCR/NLP/RAG and risk-engine prototyping.