

DAILY DRILLING REPORT (SYNTHETIC)

OIL-HPJ-009 - Hapjan-009

NWIS prototype document - not an Oil India Limited operational record

Field / Formation	Hapjan / Girujan
Report Timestamp	2017-10-07 18:00:00
Current Depth	2406.0 m
Mud System	KCl Polymer WBM
Well Risk	Low (38.0/100)
Latest Alert	Normal

Recent Drilling Parameters

Timestamp	Depth	SPP	Torque	RPM	MW	Flow In/Out	ROP	State
10-03 00:33	2244	3022	261	121	11.10	779/767	11.7	Normal
10-03 13:09	2262	2941	241	110	11.04	752/747	13.6	Normal
10-04 01:45	2280	2962	269	103	11.11	816/841	14.4	Normal
10-04 14:22	2298	3093	219	117	11.20	859/859	10.4	Normal
10-05 02:58	2316	3008	242	117	10.96	772/792	14.4	Normal
10-05 15:34	2334	2913	267	107	10.93	752/711	14.2	Normal
10-06 04:11	2352	3168	274	116	11.01	847/811	12.1	Normal
10-06 16:47	2370	2947	234	104	11.12	778/793	7.8	Normal
10-07 05:23	2388	3138	215	112	11.07	785/774	10.1	Normal
10-07 18:00	2406	2957	254	103	11.09	768/748	14.2	Normal

Operational Events / Lessons

Kick (Medium) at 1620 m: Kick at 1620 m in Girujan. Drilling break followed by positive flow check. Circulated influx under controlled conditions. Outcome: Influx circulated out and overbalance restored. Gas 207 units; pit change +8.3 bbl; mud weight 10.40 ppg. Recommended action: Set flow-check trigger for unexplained pit gain

Stuck Pipe (Medium) at 1657 m: Stuck Pipe at 1657 m in Girujan. Rotary movement deteriorated progressively. Stopped drilling and circulated bottoms-up. Outcome: Restriction cleared without fishing operation. Torque 309 kNm, drag 22.4 t, ROP 5.0 m/h. Recommended action: Plan preventive wiper trip near analogous interval

NPT (High) at 1713 m: NPT at 1713 m in Girujan. ROP dropped to zero during equipment unavailability. Isolated equipment and initiated maintenance. Outcome: Equipment restored and drilling resumed. Recommended action: Flag repeated downtime patterns before mobilization

NPT (Critical) at 2044 m: NPT at 2044 m in Girujan. No depth progress occurred during the recorded interval. Recorded downtime cause and maintenance action. Outcome: Downtime closed with maintenance record. Recommended action: Flag repeated downtime patterns before mobilization

This DDR is generated from synthetic telemetry for OCR/NLP/RAG and risk-engine prototyping.