

DAILY DRILLING REPORT (SYNTHETIC)

OIL-KMC-009 - Kumchai-009

NWIS prototype document - not an Oil India Limited operational record

Field / Formation	Kumchai / Tipam
Report Timestamp	1999-11-09 18:00:00
Current Depth	2594.0 m
Mud System	Glycol-PHPA WBM
Well Risk	Moderate (47.3/100)
Latest Alert	Normal

Recent Drilling Parameters

Timestamp	Depth	SPP	Torque	RPM	MW	Flow In/Out	ROP	State
11-04 21:04	2421	3864	273	111	11.03	744/784	16.0	Operational Variation
11-05 10:03	2441	3022	270	110	11.38	751/773	10.6	Normal
11-05 23:03	2460	3110	255	114	11.25	804/811	11.7	Normal
11-06 12:02	2479	3065	247	109	11.42	765/778	11.5	Normal
11-07 01:02	2498	3074	238	115	11.42	804/785	10.7	Normal
11-07 14:01	2517	3160	262	99	11.34	762/816	10.6	Normal
11-08 03:01	2537	3237	278	114	11.53	728/730	10.8	Normal
11-08 16:00	2556	3201	279	110	11.27	766/782	12.1	Normal
11-09 05:00	2575	3292	242	105	11.32	751/743	9.7	Normal
11-09 18:00	2594	3259	290	107	11.38	764/717	11.8	Normal

Operational Events / Lessons

Cementing Issue (High) at 1956 m: Cementing Issue at 1956 m in Tipam. Observed returns did not match calculated displacement. Reduced displacement rate and monitored returns. Outcome: Job completed with adjusted displacement plan. Cement returns 23% with density 14.74 ppg. Recommended action: Review nearby loss events before finalizing cement program

Mud Loss (Low) at 2034 m: Mud Loss at 2034 m in Tipam. Partial returns observed at shale shaker. Prepared graded lost-circulation pill. Outcome: Circulation stabilized after treatment. Flow balance: 717/687 LPM (in/out); pit change -7.2 bbl. Recommended action: Reduce pump rate/ECD before entering analogous interval

Torque Spike (Low) at 2053 m: Torque Spike at 2053 m in Tipam. High torque developed while WOB remained elevated. Adjusted rotary parameters and observed response. Outcome: Torque returned to operating band after parameter change. Torque 321 kNm, drag 14.4 t, ROP 16.7 m/h. Recommended action: Reduce WOB/RPM proactively near correlated torque-spike depth

Mud Loss (High) at 2383 m: Mud Loss at 2383 m in Tipam. Intermittent circulation losses developed while drilling ahead. Prepared graded lost-circulation pill. Outcome: Full returns restored and drilling resumed. Flow balance: 826/767 LPM (in/out); pit change -13.7 bbl. Recommended action: Reduce pump rate/ECD before entering analogous interval

This DDR is generated from synthetic telemetry for OCR/NLP/RAG and risk-engine prototyping.