

DAILY DRILLING REPORT (SYNTHETIC)

OIL-NHK-012 - Nahorkatiya-012

NWIS prototype document - not an Oil India Limited operational record

Field / Formation	Nahorkatiya / Tipam
Report Timestamp	2023-02-16 18:00:00
Current Depth	2329.0 m
Mud System	Glycol-PHPA WBM
Well Risk	Moderate (48.1/100)
Latest Alert	Normal

Recent Drilling Parameters

Timestamp	Depth	SPP	Torque	RPM	MW	Flow In/Out	ROP	State
02-11 14:18	2220	3024	258	112	10.96	818/836	7.4	Normal
02-12 04:02	2233	2886	252	104	11.07	792/791	10.8	Normal
02-12 17:47	2245	2787	219	118	11.00	802/781	12.1	Normal
02-13 07:32	2257	3017	230	106	11.12	767/788	9.8	Normal
02-13 21:16	2269	3028	222	112	11.05	840/857	12.6	Normal
02-14 11:01	2281	2926	235	116	11.16	806/817	9.4	Normal
02-15 00:46	2293	2920	262	113	11.16	821/817	13.1	Normal
02-15 14:30	2305	3016	250	108	11.18	756/756	8.2	Normal
02-16 04:15	2317	3032	252	101	11.09	804/794	14.0	Normal
02-16 18:00	2329	3160	213	109	11.19	770/781	12.8	Normal

Operational Events / Lessons

Fishing Operation (High) at 1533 m: Fishing Operation at 1533 m in Tipam. Normal pipe-recovery attempts were unsuccessful. Suspended drilling while recovery operation was executed. Outcome: Operation completed and BHA configuration reviewed. Recommended action: Review BHA reliability near correlated problematic interval

Torque Spike (Medium) at 1558 m: Torque Spike at 1558 m in Tipam. Torque rose without corresponding pressure anomaly. Paused drilling to verify BHA behaviour. Outcome: Rotary stability recovered after reaming. Torque 333 kNm, drag 15.0 t, ROP 16.7 m/h. Recommended action: Set warning on rapid torque rise with RPM instability

Stuck Pipe (High) at 1707 m: Stuck Pipe at 1707 m in Tipam. Torque and drag increased while ROP declined. Worked pipe within safe operating limits. Outcome: BHA freed and hole conditioned before drilling resumed. Torque 271 kNm, drag 37.8 t, ROP 10.5 m/h. Recommended action: Plan preventive wiper trip near analogous interval

NPT (Low) at 2051 m: NPT at 2051 m in Tipam. No depth progress occurred during the recorded interval. Switched to standby system where available. Outcome: Operational hold cleared after checks. Recommended action: Track recurring NPT cause by rig and equipment family

This DDR is generated from synthetic telemetry for OCR/NLP/RAG and risk-engine prototyping.