

WELL COMPLETION REPORT

SYNTHETIC SCANNED COPY - NWIS PROTOTYPE

Well ID: OIL-BRH-001

Well Name: Borholla-001

Field / District: Borholla / Jorhat

Formation: Girujan (GRJ)

Spud / Completion: 2007-03-24 / 2007-08-18

Measured depth / TVD: 2223 m / 2212 m

Formation interval: 1350-1916 m

Lithology: Silty shale with sandstone lenses

Mud system: Glycol-PHPA WBM

NWIS well risk: Moderate (44.7/100)

SIGNIFICANT EVENTS:

2007-06-05 | Stuck Pipe | Critical | 1204 m

Observation: High drag was recorded while circulating remained possible

Mitigation: Condition mud and verify cuttings transport before connection

Lesson: Use offset stuck-pipe depth to increase circulation and reaming frequency

2007-05-14 | NPT | High | 890 m

Observation: Rotary and WOB remained at zero during downtime

Mitigation: Verify equipment health before resuming drilling

Lesson: Recurring equipment downtime should influence planning and spares

SCANNED

WELL COMPLETION REPORT

SYNTHETIC SCANNED COPY - NWIS PROTOTYPE

Well ID: OIL-BRH-001
Well Name: Borholla-001
Field / District: Borholla / Jorhat
Formation: Girujan (GRJ)
Spud / Completion: 2007-03-24 / 2007-08-18
Measured depth / TVD: 2223 m / 2212 m
Formation interval: 1350-1916 m
Lithology: Silty shale with sandstone lenses
Mud system: Glycol-PHPA WBM
NWIS well risk: Moderate (44.7/100)

SIGNIFICANT EVENTS:

2007-06-05 | Stuck Pipe | Critical | 1204 m

Observation: High drag was recorded while circulating remained possible

Mitigation: Condition mud and verify cuttings transport before connection

Lesson: Use offset stuck-pipe depth to increase circulation and reaming frequency

2007-05-14 | NPT | High | 890 m

Observation: Rotary and WOB remained at zero during downtime

Mitigation: Verify equipment health before resuming drilling

Lesson: Recurring equipment downtime should influence planning and spares

SCANNED