

WELL COMPLETION REPORT (SYNTHETIC)

OIL-BRH-003 - Borholla-003

NWIS prototype document - not an Oil India Limited operational record

API Number	OIL-ASM-000034
Field / District	Borholla / Jorhat
Block	PEL-ASSAM-07
Basin	Assam-Arakan
Formation	Tipam (TIP)
Spud / Completion	2007-07-23 / 2007-11-28
Measured / TVD	2404 m / 2345 m
Trajectory	Vertical; inc 3.6 deg; az 33.5 deg
Formation Interval	1240-2099 m
Lithology	Sandstone-siltstone sequence
Pore Pressure Reference	2702 psi
Fracture Gradient	14.48 ppg
Mud System	Glycol-PHPA WBM
NWIS Well Risk	Moderate (52.0/100)

Casing Program

String	Set Depth (m)	Purpose
20 in conductor	80	Conductor
13 3/8 in casing	601	Surface
9 5/8 in casing	1394	Intermediate
7 in liner/casing	2115	Production

Significant Historical Events and Lessons

Date / Depth	Event	Severity	Evidence / mitigation / lesson
2007-10-19 1733 m	Kick	Critical	Drilling break followed by positive flow check. Mitigation: Re-establish overbalance and monitor pit/flow balance. Lesson: Escalate connection-gas trends before entering correlated pressure zone.
2007-11-09 2080 m	Fishing Operation	Critical	Downhole tool remained unrecovered after freeing attempts. Mitigation: Use approved fishing program with controlled overpull and circulation. Lesson: Early stuck-pipe escalation may reduce probability of fishing.
2007-09-08 1007 m	Torque Spike	High	Torque rose without corresponding pressure anomaly. Mitigation: Use staged parameter reduction to avoid torsional oscillation. Lesson: Torque-rate change is a useful precursor even when pressure is stable.
2007-09-12 1074 m	Stuck Pipe	High	Torque and drag increased while ROP declined. Mitigation: Improve hole cleaning, work pipe and back-ream within operating envelope. Lesson: Rising torque plus falling ROP should trigger hole-cleaning action.
2007-09-18 1180 m	Cementing Issue	High	Cement density/returns trend indicated placement uncertainty. Mitigation: Verify cement placement using pressure and volume balance. Lesson: Offset loss history should inform cementing hydraulics.
2007-10-02 1426 m	Torque Spike	High	Sharp torque excursion occurred with RPM instability. Mitigation: Reduce WOB/RPM and circulate before resuming normal parameters. Lesson: Use offset torque trend to set adaptive operating envelope.
2007-10-17 1687 m	Mud Loss	High	Partial returns observed at shale shaker. Mitigation: Spot graded LCM pill and circulate at reduced rate. Lesson: Prepare LCM package before approaching correlated offset-well loss depth.

Completion Summary

The synthetic well reached 2404 m MD in the Tipam interval. The NWIS knowledge record links 16 historical operational events to depth-matched telemetry. Risk classification is derived from formation, depth, trajectory and event history rather than formation alone.

This report is generated solely for SIH/NWIS prototyping and model development.