

WELL COMPLETION REPORT (SYNTHETIC)

OIL-KMC-011 - Kumchai-011

NWIS prototype document - not an Oil India Limited operational record

API Number	OIL-ASM-000132
Field / District	Kumchai / Tinsukia
Block	OALP-IV-04
Basin	Assam-Arakan
Formation	Tipam (TIP)
Spud / Completion	2017-10-24 / 2017-12-21
Measured / TVD	2574 m / 2548 m
Trajectory	Deviated; inc 26.7 deg; az 200.8 deg
Formation Interval	1608-2318 m
Lithology	Sandstone-siltstone sequence
Pore Pressure Reference	3142 psi
Fracture Gradient	14.04 ppg
Mud System	PHPA Water-Based Mud
NWIS Well Risk	Moderate (48.6/100)

Casing Program

String	Set Depth (m)	Purpose
20 in conductor	80	Conductor
13 3/8 in casing	643	Surface
9 5/8 in casing	1492	Intermediate
7 in liner/casing	2265	Production

Significant Historical Events and Lessons

Date / Depth	Event	Severity	Evidence / mitigation / lesson
2017-11-01 474 m	Kick	Critical	Unexpected background gas rise preceded influx. Mitigation: Shut in, verify influx and circulate using approved well-control procedure. Lesson: Treat pit gain plus gas increase as an early influx indicator.
2017-10-30 405 m	Torque Spike	High	Sharp torque excursion occurred with RPM instability. Mitigation: Monitor torque derivative rather than absolute torque alone. Lesson: Torque-rate change is a useful precursor even when pressure is stable.
2017-11-11 931 m	Stuck Pipe	High	High drag was recorded while circulating remained possible. Mitigation: Improve hole cleaning, work pipe and back-ream within operating envelope. Lesson: Avoid prolonged static periods in high-drag interval.
2017-12-02 1811 m	Torque Spike	High	Sharp torque excursion occurred with RPM instability. Mitigation: Use staged parameter reduction to avoid torsional oscillation. Lesson: Torque-rate change is a useful precursor even when pressure is stable.
2017-12-10 2146 m	Stuck Pipe	High	Hookload became erratic during pipe movement. Mitigation: Reduce ROP and increase circulation before high-angle interval. Lesson: Use offset stuck-pipe depth to increase circulation and reaming frequency.
2017-11-05 652 m	Fishing Operation	Medium	Normal pipe-recovery attempts were unsuccessful. Mitigation: Use approved fishing program with controlled overpull and circulation. Lesson: Early stuck-pipe escalation may reduce probability of fishing.
2017-11-09 868 m	Kick	Medium	Unexpected background gas rise preceded influx. Mitigation: Maintain trip margin and use conservative connection practices. Lesson: Escalate connection-gas trends before entering correlated pressure zone.

Completion Summary

The synthetic well reached 2574 m MD in the Tipam interval. The NWIS knowledge record links 9 historical operational events to depth-matched telemetry. Risk classification is derived from formation, depth, trajectory and event history rather than formation alone.

This report is generated solely for SIH/NWIS prototyping and model development.