

WELL COMPLETION REPORT (SYNTHETIC)

OIL-RDS-001 - Rudrasagar-001

NWIS prototype document - not an Oil India Limited operational record

API Number	OIL-ASM-000006
Field / District	Rudrasagar / Sivasagar
Block	PEL-ASSAM-06
Basin	Assam-Arakan
Formation	Girujan (GRJ)
Spud / Completion	2006-09-13 / 2007-01-19
Measured / TVD	2302 m / 2253 m
Trajectory	Vertical; inc 5.6 deg; az 113.9 deg
Formation Interval	1183-1731 m
Lithology	Silty shale with sandstone lenses
Pore Pressure Reference	2075 psi
Fracture Gradient	14.70 ppg
Mud System	Glycol-PHPA WBM
NWIS Well Risk	Low (34.5/100)

Casing Program

String	Set Depth (m)	Purpose
20 in conductor	80	Conductor
13 3/8 in casing	575	Surface
9 5/8 in casing	1335	Intermediate
7 in liner/casing	2025	Production

Significant Historical Events and Lessons

Date / Depth	Event	Severity	Evidence / mitigation / lesson
2006-12-22 1844 m	Mud Loss	Critical	Flow-out dropped below flow-in with pit loss. Mitigation: Spot graded LCM pill and circulate at reduced rate. Lesson: Prepare LCM package before approaching correlated offset-well loss depth.
2006-09-27 369 m	Torque Spike	Medium	Torque rose without corresponding pressure anomaly. Mitigation: Ream and condition hole if torque remains elevated. Lesson: Avoid simultaneous high WOB and high RPM in correlated interval.
2006-09-30 427 m	Cementing Issue	Medium	Observed returns did not match calculated displacement. Mitigation: Control displacement rate and reconcile pumped/returned volumes. Lesson: Volume imbalance is an important cement-placement warning.
2006-10-14 682 m	Cementing Issue	Medium	Cement density/returns trend indicated placement uncertainty. Mitigation: Verify cement placement using pressure and volume balance. Lesson: Plan conservative displacement rate in weak formations.
2006-10-31 981 m	Mud Loss	Medium	Flow-out dropped below flow-in with pit loss. Mitigation: Stage circulation and monitor pit volume before resuming drilling. Lesson: Prepare LCM package before approaching correlated offset-well loss depth.
2006-11-09 1132 m	Torque Spike	Medium	Sharp torque excursion occurred with RPM instability. Mitigation: Ream and condition hole if torque remains elevated. Lesson: Torque-rate change is a useful precursor even when pressure is stable.
2006-11-09 1141 m	Cementing Issue	Medium	Observed returns did not match calculated displacement. Mitigation: Review loss history before cementing equivalent interval. Lesson: Plan conservative displacement rate in weak formations.

Completion Summary

The synthetic well reached 2302 m MD in the Girujan interval. The NWIS knowledge record links 12 historical operational events to depth-matched telemetry. Risk classification is derived from formation, depth, trajectory and event history rather than formation alone.

This report is generated solely for SIH/NWIS prototyping and model development.