

DAILY DRILLING REPORT (SYNTHETIC)

OIL-BRH-009 - Borholla-009

NWIS prototype document - not an Oil India Limited operational record

Field / Formation	Borholla / Barail
Report Timestamp	2014-05-09 18:00:00
Current Depth	2764.0 m
Mud System	Low-Solids WBM
Well Risk	Moderate (45.6/100)
Latest Alert	Normal

Recent Drilling Parameters

Timestamp	Depth	SPP	Torque	RPM	MW	Flow In/Out	ROP	State
05-04 22:57	2602	3187	118	0	11.41	85/194	0.0	Precursor
05-05 11:44	2620	3314	91	0	11.21	86/110	0.0	Event
05-06 00:31	2638	3236	167	0	11.49	62/66	0.0	Recovery
05-06 13:18	2656	3048	292	112	11.83	745/747	9.4	Normal
05-07 02:05	2674	3163	283	100	11.41	786/794	14.2	Normal
05-07 14:52	2692	3434	276	107	11.38	740/731	8.3	Normal
05-08 03:39	2710	3409	275	111	11.41	728/723	12.8	Normal
05-08 16:26	2728	3392	258	98	11.47	792/810	5.0	Normal
05-09 05:13	2746	3199	273	119	11.39	756/747	12.1	Normal
05-09 18:00	2764	3368	265	108	11.51	761/745	9.2	Normal

Operational Events / Lessons

Cementing Issue (High) at 2057 m: Cementing Issue at 2057 m in Barail. Observed returns did not match calculated displacement. Extended observation of returns before concluding job. Outcome: Returns improved after rate reduction. Cement returns 56% with density 13.67 ppg. Recommended action: Use pressure-volume reconciliation during displacement

Mud Loss (High) at 2112 m: Mud Loss at 2112 m in Barail. Flow-out dropped below flow-in with pit loss. Reduced ROP and conditioned the hole. Outcome: Circulation stabilized after treatment. Flow balance: 755/657 LPM (in/out); pit change -17.3 bbl. Recommended action: Reduce pump rate/ECD before entering analogous interval

Mud Loss (Low) at 2530 m: Mud Loss at 2530 m in Barail. Partial returns observed at shale shaker. Reduced pump rate and monitored active pits. Outcome: Circulation stabilized after treatment. Flow balance: 844/816 LPM (in/out); pit change -4.7 bbl. Recommended action: Pre-stage LCM and set early-warning threshold on flow-out deficit

NPT (Medium) at 2620 m: NPT at 2620 m in Barail. No depth progress occurred during the recorded interval. Recorded downtime cause and maintenance action. Outcome: Downtime closed with maintenance record. Recommended action: Track recurring NPT cause by rig and equipment family

This DDR is generated from synthetic telemetry for OCR/NLP/RAG and risk-engine prototyping.