

DAILY DRILLING REPORT (SYNTHETIC)

OIL-DGB-004 - Digboi-004

NWIS prototype document - not an Oil India Limited operational record

Field / Formation	Digboi / Tipam
Report Timestamp	2021-06-30 18:00:00
Current Depth	2558.0 m
Mud System	PHPA Water-Based Mud
Well Risk	Low (35.0/100)
Latest Alert	Normal

Recent Drilling Parameters

Timestamp	Depth	SPP	Torque	RPM	MW	Flow In/Out	ROP	State
06-25 20:13	2473	3234	250	110	11.18	722/684	8.8	Normal
06-26 09:18	2483	3110	280	94	11.28	733/742	11.6	Normal
06-26 22:23	2492	3085	217	113	11.17	796/796	12.2	Normal
06-27 11:28	2502	3227	269	100	11.27	745/751	12.3	Normal
06-28 00:34	2511	3127	239	103	11.43	759/763	12.8	Normal
06-28 13:39	2520	3166	249	113	11.33	807/813	10.5	Normal
06-29 02:44	2530	3086	278	105	11.14	803/809	9.8	Normal
06-29 15:49	2539	3126	263	114	11.43	716/710	12.2	Normal
06-30 04:54	2549	3156	259	101	11.19	800/814	10.5	Normal
06-30 18:00	2558	3385	286	103	11.32	772/762	10.9	Normal

Operational Events / Lessons

Mud Loss (Medium) at 2094 m: Mud Loss at 2094 m in Tipam. Active pit volume declined during stable pump rate. Stopped drilling and performed flow check. Outcome: Circulation stabilized after treatment. Flow balance: 816/719 LPM (in/out); pit change -3.1 bbl. Recommended action: Pre-stage LCM and set early-warning threshold on flow-out deficit

Stuck Pipe (Medium) at 2132 m: Stuck Pipe at 2132 m in Tipam. High drag was recorded while circulating remained possible. Back-reamed cautiously while monitoring torque. Outcome: Restriction cleared without fishing operation. Torque 296 kNm, drag 17.5 t, ROP 9.3 m/h. Recommended action: Increase hole-cleaning surveillance before this depth

Mud Loss (High) at 2180 m: Mud Loss at 2180 m in Tipam. Partial returns observed at shale shaker. Prepared graded lost-circulation pill. Outcome: Loss rate reduced to acceptable level. Flow balance: 754/709 LPM (in/out); pit change -15.1 bbl. Recommended action: Pre-stage LCM and set early-warning threshold on flow-out deficit

Torque Spike (Medium) at 2304 m: Torque Spike at 2304 m in Tipam. Sharp torque excursion occurred with RPM instability. Adjusted rotary parameters and observed response. Outcome: Drilling resumed at reduced mechanical loading. Torque 334 kNm, drag 10.9 t, ROP 14.6 m/h. Recommended action: Reduce WOB/RPM proactively near correlated torque-spike depth

This DDR is generated from synthetic telemetry for OCR/NLP/RAG and risk-engine prototyping.