

DAILY DRILLING REPORT (SYNTHETIC)

OIL-DRK-011 - Dirok-011

NWIS prototype document - not an Oil India Limited operational record

Field / Formation	Dirok / Girujan
Report Timestamp	2018-09-24 18:00:00
Current Depth	2303.0 m
Mud System	Low-Solids WBM
Well Risk	Low (39.2/100)
Latest Alert	Normal

Recent Drilling Parameters

Timestamp	Depth	SPP	Torque	RPM	MW	Flow In/Out	ROP	State
09-20 07:31	2216	2946	253	105	11.07	784/805	12.7	Normal
09-20 19:21	2226	2885	232	108	10.91	843/814	12.9	Normal
09-21 07:11	2235	3091	243	116	10.85	763/788	10.9	Normal
09-21 19:01	2245	2953	234	112	11.08	775/792	8.1	Normal
09-22 06:50	2255	2847	244	102	11.10	788/815	10.3	Normal
09-22 18:40	2264	3053	253	97	11.26	808/781	8.3	Normal
09-23 06:30	2274	3027	284	111	11.00	739/731	10.7	Normal
09-23 18:20	2284	2916	224	110	10.90	734/721	9.1	Normal
09-24 06:10	2293	3026	197	106	10.99	785/777	6.3	Normal
09-24 18:00	2303	2773	260	110	11.03	749/764	9.2	Normal

Operational Events / Lessons

Cementing Issue (Low) at 1727 m: Cementing Issue at 1727 m in Girujan. Cement returns were below planned percentage. Verified volumes and adjusted cementing rate. Outcome: Returns improved after rate reduction. Cement returns 38% with density 14.22 ppg. Recommended action: Alert when cement-return percentage drops below expected envelope

Torque Spike (Medium) at 1845 m: Torque Spike at 1845 m in Girujan. Torque rose without corresponding pressure anomaly. Reduced WOB and RPM. Outcome: Drilling resumed at reduced mechanical loading. Torque 280 kNm, drag 10.8 t, ROP 9.3 m/h. Recommended action: Set warning on rapid torque rise with RPM instability

Kick (High) at 1865 m: Kick at 1865 m in Girujan. Unexpected background gas rise preceded influx. Shut in well and recorded pressures. Outcome: Operations resumed after well-control verification. Gas 222 units; pit change +13.2 bbl; mud weight 10.58 ppg. Recommended action: Set flow-check trigger for unexplained pit gain

Mud Loss (High) at 1973 m: Mud Loss at 1973 m in Girujan. Partial returns observed at shale shaker. Prepared graded lost-circulation pill. Outcome: Circulation stabilized after treatment. Flow balance: 694/542 LPM (in/out); pit change -2.9 bbl. Recommended action: Monitor pit volume continuously within +/-50 m of this depth

This DDR is generated from synthetic telemetry for OCR/NLP/RAG and risk-engine prototyping.