

DAILY DRILLING REPORT (SYNTHETIC)

OIL-DRK-012 - Dirok-012

NWIS prototype document - not an Oil India Limited operational record

Field / Formation	Dirok / Tipam
Report Timestamp	2003-05-10 18:00:00
Current Depth	2496.0 m
Mud System	Low-Solids WBM
Well Risk	Moderate (43.0/100)
Latest Alert	Normal

Recent Drilling Parameters

Timestamp	Depth	SPP	Torque	RPM	MW	Flow In/Out	ROP	State
05-07 07:24	2327	3061	338	89	11.16	778/776	14.8	Precursor
05-07 16:35	2346	3046	366	99	11.16	714/685	12.8	Event
05-08 01:45	2365	2899	319	93	11.24	802/774	12.7	Recovery
05-08 10:56	2384	3120	250	103	11.11	769/768	8.0	Normal
05-08 20:07	2402	2932	290	110	11.19	738/712	12.2	Normal
05-09 05:17	2421	3045	237	104	11.16	722/703	12.9	Normal
05-09 14:28	2440	3107	288	107	11.09	803/823	12.8	Normal
05-09 23:38	2459	3039	244	107	11.09	785/787	12.1	Normal
05-10 08:49	2477	2979	254	112	11.27	750/735	13.0	Normal
05-10 18:00	2496	3152	276	105	11.22	707/699	12.8	Normal

Operational Events / Lessons

Kick (High) at 1834 m: Kick at 1834 m in Tipam. Flow-out exceeded flow-in and gas units increased. Circulated influx under controlled conditions. Outcome: Influx circulated out and overbalance restored. Gas 187 units; pit change +15.5 bbl; mud weight 10.71 ppg. Recommended action: Raise kick advisory when flow-out exceeds flow-in with rising gas

Stuck Pipe (Medium) at 1929 m: Stuck Pipe at 1929 m in Tipam. Torque and drag increased while ROP declined. Worked pipe within safe operating limits. Outcome: BHA freed and hole conditioned before drilling resumed. Torque 308 kNm, drag 21.7 t, ROP 8.0 m/h. Recommended action: Increase hole-cleaning surveillance before this depth

Kick (Critical) at 2025 m: Kick at 2025 m in Tipam. Drilling break followed by positive flow check. Increased monitoring frequency and prepared kill-weight mud. Outcome: Operations resumed after well-control verification. Gas 209 units; pit change +7.0 bbl; mud weight 10.81 ppg. Recommended action: Raise kick advisory when flow-out exceeds flow-in with rising gas

Torque Spike (Medium) at 2346 m: Torque Spike at 2346 m in Tipam. Sharp torque excursion occurred with RPM instability. Reduced WOB and RPM. Outcome: Torque returned to operating band after parameter change. Torque 366 kNm, drag 16.1 t, ROP 12.8 m/h. Recommended action: Set warning on rapid torque rise with RPM instability

This DDR is generated from synthetic telemetry for OCR/NLP/RAG and risk-engine prototyping.