

DAILY DRILLING REPORT (SYNTHETIC)

OIL-KMC-003 - Kumchai-003

NWIS prototype document - not an Oil India Limited operational record

Field / Formation	Kumchai / Girujan
Report Timestamp	2001-12-18 18:00:00
Current Depth	2012.0 m
Mud System	KCl Polymer WBM
Well Risk	Low (38.6/100)
Latest Alert	Normal

Recent Drilling Parameters

Timestamp	Depth	SPP	Torque	RPM	MW	Flow In/Out	ROP	State
12-15 00:09	1877	2566	207	96	10.53	742/745	13.2	Normal
12-15 10:08	1892	2674	226	112	10.60	805/834	7.7	Normal
12-15 20:07	1907	2617	197	111	10.73	795/766	10.0	Normal
12-16 06:06	1922	2625	203	112	10.84	832/809	8.8	Normal
12-16 16:05	1937	2593	237	110	10.74	825/809	9.7	Operational Variation
12-17 02:04	1952	2756	232	122	10.83	828/831	9.5	Normal
12-17 12:03	1967	2591	162	112	10.84	728/749	11.2	Normal
12-17 22:02	1982	2908	230	113	10.89	773/776	10.3	Normal
12-18 08:01	1997	2793	279	101	10.66	768/766	11.6	Normal
12-18 18:00	2012	2660	194	121	10.61	777/767	13.4	Normal

Operational Events / Lessons

Stuck Pipe (Medium) at 1421 m: Stuck Pipe at 1421 m in Girujan. Hookload became erratic during pipe movement. Reduced WOB and increased hole-cleaning circulation. Outcome: Pipe movement restored after circulation and working. Torque 207 kNm, drag 27.4 t, ROP 5.6 m/h. Recommended action: Trigger stuck-pipe warning on combined torque/drag/ROP deterioration

Stuck Pipe (High) at 1590 m: Stuck Pipe at 1590 m in Girujan. Torque and drag increased while ROP declined. Worked pipe within safe operating limits. Outcome: Restriction cleared without fishing operation. Torque 300 kNm, drag 17.2 t, ROP 3.7 m/h. Recommended action: Plan preventive wiper trip near analogous interval

NPT (Medium) at 1620 m: NPT at 1620 m in Girujan. No depth progress occurred during the recorded interval. Isolated equipment and initiated maintenance. Outcome: Downtime closed with maintenance record. Recommended action: Track recurring NPT cause by rig and equipment family

Torque Spike (Medium) at 1741 m: Torque Spike at 1741 m in Girujan. Torque rose without corresponding pressure anomaly. Reduced WOB and RPM. Outcome: Spike cleared with no equipment damage. Torque 302 kNm, drag 9.0 t, ROP 14.1 m/h. Recommended action: Set warning on rapid torque rise with RPM instability

This DDR is generated from synthetic telemetry for OCR/NLP/RAG and risk-engine prototyping.