

DAILY DRILLING REPORT (SYNTHETIC)

OIL-MRN-001 - Moran-001

NWIS prototype document - not an Oil India Limited operational record

Field / Formation	Moran / Tipam
Report Timestamp	2003-05-13 18:00:00
Current Depth	2580.0 m
Mud System	PHPA Water-Based Mud
Well Risk	Moderate (49.5/100)
Latest Alert	Normal

Recent Drilling Parameters

Timestamp	Depth	SPP	Torque	RPM	MW	Flow In/Out	ROP	State
05-08 19:16	2451	2759	235	100	11.12	800/740	8.8	Precursor
05-09 08:27	2466	2679	222	121	11.36	852/785	9.9	Event
05-09 21:39	2480	3098	286	101	11.37	802/791	7.8	Recovery
05-10 10:50	2494	3089	235	112	11.43	843/843	13.2	Normal
05-11 00:02	2508	3208	275	114	11.28	761/739	10.3	Normal
05-11 13:13	2523	3382	250	114	11.18	763/748	12.1	Normal
05-12 02:25	2537	3175	252	116	11.37	751/775	13.2	Normal
05-12 15:36	2551	3239	240	105	11.37	724/719	10.2	Normal
05-13 04:48	2566	3071	240	118	11.33	743/731	12.9	Normal
05-13 18:00	2580	3201	234	110	11.43	784/784	10.7	Normal

Operational Events / Lessons

Pressure Spike (Medium) at 1929 m: Pressure Spike at 1929 m in Tipam. Short-duration high-pressure excursion was recorded. Verified surface equipment and mud properties. Outcome: Restriction cleared without further escalation. SPP 3662 psi at flow-in 685 LPM. Recommended action: Reduce pump rate and verify circulation if pressure trend persists

Fishing Operation (Medium) at 2090 m: Fishing Operation at 2090 m in Tipam. Downhole tool remained unrecovered after freeing attempts. Prepared fishing assembly and recovery plan. Outcome: Fish recovered and hole conditioned. Recommended action: Keep offset fishing history visible to BHA planning team

Mud Loss (High) at 2408 m: Mud Loss at 2408 m in Tipam. Intermittent circulation losses developed while drilling ahead. Stopped drilling and performed flow check. Outcome: Full returns restored and drilling resumed. Flow balance: 841/682 LPM (in/out); pit change -16.9 bbl. Recommended action: Monitor pit volume continuously within +/-50 m of this depth

Mud Loss (Medium) at 2466 m: Mud Loss at 2466 m in Tipam. Partial returns observed at shale shaker. Prepared graded lost-circulation pill. Outcome: Full returns restored and drilling resumed. Flow balance: 852/785 LPM (in/out); pit change -12.2 bbl. Recommended action: Pre-stage LCM and set early-warning threshold on flow-out deficit

This DDR is generated from synthetic telemetry for OCR/NLP/RAG and risk-engine prototyping.