

DAILY DRILLING REPORT (SYNTHETIC)

OIL-NHK-004 - Nahorkatiya-004

NWIS prototype document - not an Oil India Limited operational record

Field / Formation	Nahorkatiya / Tipam
Report Timestamp	1999-08-14 18:00:00
Current Depth	2857.0 m
Mud System	PHPA Water-Based Mud
Well Risk	Moderate (47.9/100)
Latest Alert	Normal

Recent Drilling Parameters

Timestamp	Depth	SPP	Torque	RPM	MW	Flow In/Out	ROP	State
08-09 21:38	2695	3120	279	118	11.41	864/882	10.7	Normal
08-10 10:33	2713	4211	237	105	11.64	823/780	8.6	Operational Variation
08-10 23:29	2731	3306	230	119	11.70	787/805	10.0	Normal
08-11 12:25	2749	3378	272	104	11.56	749/762	18.2	Normal
08-12 01:21	2767	3412	294	111	11.35	809/815	11.1	Normal
08-12 14:16	2785	3194	242	110	11.42	827/838	12.2	Normal
08-13 03:12	2803	3147	230	114	11.77	823/824	13.2	Normal
08-13 16:08	2821	3283	278	102	11.61	686/669	13.4	Normal
08-14 05:04	2839	3231	235	107	11.45	798/823	13.1	Normal
08-14 18:00	2857	3255	279	101	11.84	742/745	9.0	Normal

Operational Events / Lessons

Torque Spike (Medium) at 1471 m: Torque Spike at 1471 m in Tipam. Rotary speed fluctuated during constant pump rate. Adjusted rotary parameters and observed response. Outcome: Torque returned to operating band after parameter change. Torque 232 kNm, drag 14.1 t, ROP 11.3 m/h. Recommended action: Reduce WOB/RPM proactively near correlated torque-spike depth

Torque Spike (Critical) at 1887 m: Torque Spike at 1887 m in Tipam. Torque rose without corresponding pressure anomaly. Reamed short interval and circulated cuttings. Outcome: Drilling resumed at reduced mechanical loading. Torque 313 kNm, drag 17.5 t, ROP 11.2 m/h. Recommended action: Compare live torque derivative with offset-well baseline

Torque Spike (Medium) at 2184 m: Torque Spike at 2184 m in Tipam. High torque developed while WOB remained elevated. Adjusted rotary parameters and observed response. Outcome: Rotary stability recovered after reaming. Torque 310 kNm, drag 12.6 t, ROP 14.4 m/h. Recommended action: Set warning on rapid torque rise with RPM instability

Cementing Issue (Medium) at 2239 m: Cementing Issue at 2239 m in Tipam. Displacement pressure became unstable. Reduced displacement rate and monitored returns. Outcome: Returns improved after rate reduction. Cement returns 34% with density 15.70 ppg. Recommended action: Alert when cement-return percentage drops below expected envelope

This DDR is generated from synthetic telemetry for OCR/NLP/RAG and risk-engine prototyping.