

DAILY DRILLING REPORT (SYNTHETIC)

OIL-RDS-011 - Rudrasagar-011

NWIS prototype document - not an Oil India Limited operational record

Field / Formation	Rudrasagar / Tipam
Report Timestamp	2011-04-16 18:00:00
Current Depth	2559.0 m
Mud System	Glycol-PHPA WBM
Well Risk	Moderate (48.5/100)
Latest Alert	Normal

Recent Drilling Parameters

Timestamp	Depth	SPP	Torque	RPM	MW	Flow In/Out	ROP	State
04-12 01:23	2479	2954	247	107	11.20	796/781	14.2	Normal
04-12 13:54	2488	3164	276	109	11.18	783/813	12.5	Normal
04-13 02:25	2497	3176	268	101	11.36	831/803	11.4	Operational Variation
04-13 14:55	2506	3167	222	110	11.19	846/839	11.7	Normal
04-14 03:26	2515	3038	267	110	11.42	778/810	9.1	Normal
04-14 15:57	2524	3135	273	103	11.44	769/760	12.5	Operational Variation
04-15 04:27	2532	3072	254	111	11.27	771/786	6.4	Normal
04-15 16:58	2541	3065	300	107	11.37	779/768	8.7	Operational Variation
04-16 05:29	2550	3178	254	111	11.50	785/790	11.0	Normal
04-16 18:00	2559	3078	290	105	11.37	747/761	14.1	Normal

Operational Events / Lessons

Cementing Issue (Medium) at 2086 m: Cementing Issue at 2086 m in Tipam. Observed returns did not match calculated displacement. Extended observation of returns before concluding job. Outcome: Job completed with adjusted displacement plan. Cement returns 55% with density 14.39 ppg. Recommended action: Use pressure-volume reconciliation during displacement

Cementing Issue (Critical) at 2417 m: Cementing Issue at 2417 m in Tipam. Displacement pressure became unstable. Verified volumes and adjusted cementing rate. Outcome: Job completed with adjusted displacement plan. Cement returns 39% with density 15.82 ppg. Recommended action: Alert when cement-return percentage drops below expected envelope

Pressure Spike (High) at 2435 m: Pressure Spike at 2435 m in Tipam. Circulating pressure climbed without equivalent torque change. Verified surface equipment and mud properties. Outcome: Standpipe pressure normalized after circulation. SPP 4078 psi at flow-in 803 LPM. Recommended action: Reduce pump rate and verify circulation if pressure trend persists

Mud Loss (Medium) at 2444 m: Mud Loss at 2444 m in Tipam. Active pit volume declined during stable pump rate. Prepared graded lost-circulation pill. Outcome: Circulation stabilized after treatment. Flow balance: 710/632 LPM (in/out); pit change -11.3 bbl. Recommended action: Pre-stage LCM and set early-warning threshold on flow-out deficit

This DDR is generated from synthetic telemetry for OCR/NLP/RAG and risk-engine prototyping.