

WELL COMPLETION REPORT (SYNTHETIC)

OIL-BGJ-011 - Baghjan-011

NWIS prototype document - not an Oil India Limited operational record

API Number	OIL-ASM-000129
Field / District	Baghjan / Tinsukia
Block	OALP-IV-03
Basin	Assam-Arakan
Formation	Tipam (TIP)
Spud / Completion	2003-09-03 / 2004-01-14
Measured / TVD	2814 m / 2778 m
Trajectory	Vertical; inc 1.3 deg; az 220.0 deg
Formation Interval	1418-2363 m
Lithology	Fine-medium sandstone with shale interbeds
Pore Pressure Reference	3060 psi
Fracture Gradient	15.02 ppg
Mud System	Low-Solids WBM
NWIS Well Risk	Moderate (45.3/100)

Casing Program

String	Set Depth (m)	Purpose
20 in conductor	80	Conductor
13 3/8 in casing	703	Surface
9 5/8 in casing	1632	Intermediate
7 in liner/casing	2476	Production

Significant Historical Events and Lessons

Date / Depth	Event	Severity	Evidence / mitigation / lesson
2003-11-24 1839 m	Kick	High	Pit gain and flow with pumps off were observed. Mitigation: Shut in, verify influx and circulate using approved well-control procedure. Lesson: Maintain mud-weight window using offset pressure evidence.
2003-12-27 2473 m	Stuck Pipe	High	High drag was recorded while circulating remained possible. Mitigation: Condition mud and verify cuttings transport before connection. Lesson: Rising torque plus falling ROP should trigger hole-cleaning action.
2004-01-01 2563 m	Torque Spike	High	Rotary speed fluctuated during constant pump rate. Mitigation: Monitor torque derivative rather than absolute torque alone. Lesson: Use offset torque trend to set adaptive operating envelope.
2003-11-25 1849 m	Mud Loss	Medium	Flow-out dropped below flow-in with pit loss. Mitigation: Optimize hydraulics and maintain conservative ROP through loss interval. Lesson: Prepare LCM package before approaching correlated offset-well loss depth.
2003-12-04 2035 m	Torque Spike	Medium	Sharp torque excursion occurred with RPM instability. Mitigation: Reduce WOB/RPM and circulate before resuming normal parameters. Lesson: Avoid simultaneous high WOB and high RPM in correlated interval.
2003-12-11 2158 m	Cementing Issue	Medium	Observed returns did not match calculated displacement. Mitigation: Review loss history before cementing equivalent interval. Lesson: Volume imbalance is an important cement-placement warning.
2003-12-12 2188 m	Kick	Medium	Drilling break followed by positive flow check. Mitigation: Increase mud weight within fracture-margin limits and monitor gas trend. Lesson: Treat pit gain plus gas increase as an early influx indicator.

Completion Summary

The synthetic well reached 2814 m MD in the Tipam interval. The NWIS knowledge record links 12 historical operational events to depth-matched telemetry. Risk classification is derived from formation, depth, trajectory and event history rather than formation alone.

This report is generated solely for SIH/NWIS prototyping and model development.