CALDERWICK PUMP SYSTEMS LTD

Ardmoor Plant Report, September 2025

Document code	OPS-P2-2025-09
Site	Plant P2, Ardmoor (test and calibration)
Prepared by	Plant Manager, Ardmoor (P2)
Date	6 October 2025
Classification	Internal

1. Summary

Calderwick Pump Systems Ltd's Ardmoor plant completed 151 customer tests in September 2025 against a plan of 155. Rig TR-1 was degraded for two days after a hydraulic leak on 9 September (incident INC-2025-021). Rig TR-5, transferred from Hollins Cross, entered service on 29 September.

2. Key figures

Table 1 - September 2025

Measure	September 2025	Plan or target
Customer tests completed	151	155
Rig availability TR-1	91.8%	97%
Rig availability TR-2	99.2%	97%
Rig availability TR-3	98.7%	97%
Rig availability TR-4	99.1%	97%
Average rig availability (TR-1 to TR-4)	97.2%	97%
Lost-time injuries	0	0
First-aid cases	1	-
Headcount at month end	66	66

TR-5 is not included in the September availability figures because it entered service on the last working days of the month.

3. Incidents

- 9 to 11 September: TR-1 ran with reduced pressure after a hydraulic leak (INC-2025-021). The maintenance supplier arrived 6 hours 30 minutes after the call and the rig was fully restored on 11 September at 10:00.
- 17 September: a technician cut a hand on a sharp bracket; first aid only.

4. Supplier and projects

After two missed service levels in two months, the maintenance contract with Brennock Valve Services Ltd was amended from 1 October 2025: TR-5 is added, the P1 restore time is shortened to 6 hours and an on-call engineer covers Ardmoor from 07:00 to 22:00. The PRJ-11 design review with Ardent Controls Ltd took place on 24 September; design freeze was confirmed for 30 September.