### **BMW Bedfordview**



### Parts Tax Invoice

M.A.G. MOTOR ACCIDENT GROUM.A.G. MOTOR ACCIDENT GROUP

P.O BOX 38227

P.O BOX 38227

2016 BOOYENS

2016

**BOOYENS** 

Invoice no. Account no. 40139644

Order no.

100560

ML1001589

**Document Date** 

23/12/2020

Document Time.

13:18

WIP no.

57813

011 493 9160

Page

Model Description

VAT Reg no: 4730232263

Reg no.

Reg. Date Chassis no. Mileage

You were served by

Nischal Maharaj

itan	Part number	Description	6ln	Qty	Unit price Y	Disc	Amount
2	B 51 23 7 313 782 B 51 23 7 411 315 B 51 45 9 241 178 B 51 23 7 309 608	BONNET CABLE BONNET CABLE INSTR PANEL CTR CVR BONNET LEVER	W02A W01C ZZZZ ZZZZ	1.00 1.00 1.00 1.00	301.73 S 301.73 S 247.64 S 315.88 S		301.73 301.73 247.64 315.88

Phase IV Motor Investments (Pty) Ltd.

> Trading As BMW Bedfordview

> > Registration No 2002/016444/07

> > > VAT Reg. No. 4560202139

Telephone 011 201-0000

Facsimile 011 201-0050 011 201-0049

Postal Address P.O. Box 751598 Garden View 2047


Street Address 8 Kings Road Bedfordview

Internet www.bmw-bedfordview.co.za

> Dealer Principal G Kilfoil

Directors V Vermaak GR Vermaak **BM Mathabathe** 

Banking Details Phase IV Motor Investments (PTY) LTD FNB Account 62046519627 Branch



BMW Parts Exch. perts	Other Parts Lubricants	Misc LifeStyle	Disc.	VAT Code	VAT	Net Amount	VAT
1166.98 0.00	0.00 0.00	0.00	0.00	s	15.00	1166.98	175.05
Notes:	The last the second second second		1 Part	Ket Amou		VAT	Grand Total
	PICKED SY	-		1166.	•	175.05	1342.03
	N. Contraction		or property and property and the second			Paid	0.00
	CHECKED B.	1	A CONTRACTOR OF THE PARTY OF TH			Owing	1342.03

# Parts Tax Invoice

1 B51 21 1 852 140 LH INTSTRUMENT PANEL 2 B51 47 8 184 135 RH INSTRUMENT PANEL 3 B51 131 973 253 CENTRE CONTOL 4 B61 72 7 047 349 RF CENTRE CONSOLE 5 B51 77 7 200 849 CENTRE CONSOLE 6 B51 47 1 930 724 RH CENTRE CONSOLE 7 B51 47 1 933 558 RIR BACKREST TRIM				011 493 9160	VAT Reg no: 4730232263		2016		•	M.A.G. MOTOR ACCIDENT GROUN.A.G. MOTOR ACCIDENT GROUP P.O BOX 38227 P.O BOX 38227
MED7H MC08A A01F P01 R04 W03A A03G	(A)		e E							ENT GROU
######################################	196			Page	W.	Do	8	On	Aα	
201.50 S 201.50 S 3985.70 S 1096.70 S 4186.91 S 908.80 S 2412.09 S	Undiguese V			ge	WIP no.	Document Time.	Document Date	Order no.	Account no.	Invoice no.
201.50 5 201.50 6 3985.70 1 1986.70 1 4188.91 6 908.60 1 2412.08 [2	DESCRIPTION NAMED IN	Nischal Maharaj		-	59904	14:00	25/01/2021	ML1001589	100580	49140277
N = 0 = 0										

Baraking Debalis Plass IV Mator I newstramts (PT1) LT1 (PT1) LT1 Axoust Mator 630489 IBSZT 630486 IBSZT 630486 IBSZT 630486 IBSZT	Directors V Vermask GR Vermask M Vormesk M Vermesk BM Methysbuthe	iyeevi.brite-bedfordview.co.zz Deater Principal G Kificil	Street Address 8 Kings Road Bedicrivies 2007 Internet	Postal Address P.O. Box 761688 Garden Vew 2047	Facsinile 911 201-0380 911 201-0048	Telaphona 011 201-0000	VAT Reg. No. 4580202139	Pagistration No 2002/018444/07	Trading As	Physe & Motor Invesimants (Pty) Ltd.	
	Notes:	12992	1								

	Luncon.	ü		8 5	<b>v</b> 4		
12982.00	0.00	0.00	0.00	Ç	15.00	12592.00	1946.80
tes:				12692.00	00	1948.80	14940,80
						Paid	0.00
						Qwing	14940.80

[1+2]

	TAX	INVO	ICE .	Nº	_ , 3	916	
1	 _	3116					

# FAST N FURIOUS LOCKSMITH

CK: 2011/077176/23 VAT No. 4480266933



CELL: 074 699 6347 / 074 194 5410 EMAIL: fastnfuriouslocksmith@gmail.com



MOTOR ACCIDENT D	2/	112/2	220
GROUP	al <del>o z</del>		
Address:			
MI INNICED			************
City Item .	ell:		
	Price	Amou	FRL.
CANONT 20 ATT Za BMN F30 CA	18/	144	
NO KG/	-		
CM AN PROCRAMME	<del> </del>		
2x NEN REMOTE	4	<del> </del>	+-1
	-	-	-
JABon & Have		10200	00
	<u> </u>		-
			+
BANKING DETAILS:	ıb Tot-l	100	
EDBANK - FORDSBURG  CHEQUE ACCOUNT	ובנוסו סג	1530	00
ACC. No.: 1036653811 Branch Code: 195305	TOTAL	11730	00
Dialicit Code. 190300	. Le	170	E.&ÖE

# Standard Bank of South Africa Tre Standard Bank of South Africa

ComputerGeneratedCopy

Total Batch amount Total RTGS Processed Total RTC Processed Total RTGS Rejected Total RTC Rejected Hash Total	Total Batcherror free records	Trans No	Capturing operator id Sub-batch 001	User Name	User id	Customer no	
4 4 4	ords	Acc No / CDI 1036653811	ratorid PRU21	MAGIN	QXR32	200101860	
11,730.00 0 0 0 1215994920303000	11,730.00	Branch No 195305		MAG INVESTMENTS		860	
000		ACCOUNT NO 0000281711623 ACCOUNT Name Su FAST & FURIOUS LOCKSMITH MI					CUSTOMER
		Statement Ref. MOTOR ACCIDENT /3916	Reference 2020356018 Action Date 2020/12/21				CUSTOMER ALL PAYMENTS INTERIM ALIDIT REPORT
Amount Amount Amount		Amount 11,730.00					
# 0.00 # 0.00		From Account Name JA MAG INVESTMENTS CC DOUGL Status Description Code Creditor Code VALIDATED - ADDITION MAG561	Tim				TGCGRG
		Creditor Code MAG561	Time 14:14:58				
		RTGS/RTC					
		Pay Alert					

"DISCLAIMER "

THIS IS AN INTERIM AUDIT REPORT INTENDED FOR RECORD KEEPING PURPOSES ONLY AND IS NOT A PROOF OF PAYMENT

Make sure that you have entered the correct account number as we will pay to, or collect from, the account number you entered. Banks do not obeck that the specified account number and account name match, Accordingly, Standard Bank cannot be held responsible for payments going to, or collections being taken from, an incorrect account number should incorrect or fraudulent account details be entered. If your Standard Bank representative about our account verification services.

\*\* END OF REPORT \*\*



### Vehicle Diagnostic Report The Report is created by LAUNC

### Repair Shop

Shop Name:mmMotor Accident Group

Address:80 Booysens Road Selby Johannesburg Gauteng

Zip Code:2001

Telephone:010-591-7550

Email:info@motoraccidentgroup.co.za

SN:989280017619

Test Time:2021-01-25 12:38:30



### Vehicle Information

License #:CN18NVGP

Year:2013.06 Make:BMW

Model:320d

VIN:WBA3D36070NN69387

Odometer:94917 km

Vehicle Software Version: V50.54

Diagnostic Application Version: V7.03.002

Diagnostic path: Automatically Search > Health Report



Permanent



### Inspection Result

CAS (Car Access System - CAS/FEM/BDC) 3 problems exist

1.804080 Ignition On: Startability Limit Reached Or Ignition On For Permanent A Long Time.

2.8040B7 De-Activation Of Terminal 15: Top Startability Limit Intermittent

Reached

3.8040B9 De-Activation Of Terminal 30B: Top Startability Limit Intermittent Reached

ECM (Engine Control Module - DME/DDE) 2 problems exist

1.2A1100 Alternator: Mechanical Fault Intermittent 2.288F00 Power Management: Reduction Or Shutdown Of Intermittent

Individual Current Consumers

ZBE/CON (Controller) 2 problems exist

1.801408 CON: No Current Coding Data Stored Permanent 2.801403 CON: Control Unit Is Not Encoded For The Vehicle

AC (Air Conditioning - IHKA) 1 problems exist

1.8011FA Electric Auxiliary Heater: Undervoltage Or Overvoltage Intermittent

Detected

The following systems are OK:

1.EKPS (Electronic Fuel Pump)/RLM\_1L (Tail Light Module, Outer Left)

- 2.ICM (Integrated Chassis Management)/RLM\_2L (Tail Light Module, Inner Left)
- 3.ABS (Anti-Lock Braking System DSC)
- 4.EPS (Electronic Power Steering)
- 5.SRS (Supplemental Inflatable Restraint System AIRBAG/SGM-SIM)
- 6.ZGM (Central Gateway Module)
- 7.FZD (Function Center, Roof)
- 8.IC (Instrument Cluster INSTR)
- 9.CIC (Car Information Computer)
- 10.FRM (Footwell Module)



# Vehicle Diagnostic Report The Report is created by LAUNCH X431

### **Repair Shop**

Shop Name:mmMotor Accident Group

Address:80 Booysens Road Selby Johannesburg Gauteng

Zip Code:2001

Telephone:010-591-7550

Email:info@motoraccidentgroup.co.za

SN:989280017619

Test Time:2021-01-25 12:40:25



### **Vehicle Information**

License #:CN18NVGP

Year:2013.06 Make:BMW Model:320d

VIN:WBA3D36070NN69387

Odometer:94917 km

Vehicle Software Version: V50.54

Diagnostic Application Version: V7.03.002

Diagnostic path: Automatically Search > Health Report





### **Inspection Result**

The following systems are OK:

- 1.EKPS (Electronic Fuel Pump)/RLM\_1L (Tail Light Module, Outer Left)
- 2.ICM (Integrated Chassis Management)/RLM\_2L (Tail Light Module, Inner Left)
- 3.ABS (Anti-Lock Braking System DSC)
- 4.EPS (Electronic Power Steering)
- 5.SRS (Supplemental Inflatable Restraint System = AIRBAG/SGM-SIM)
- 6.ZGM (Central Gateway Module)
- 7.FZD (Function Center, Roof)
- 8.CIC (Car Information Computer)
- 9.CAS (Car Access System CAS/FEM/BDC)
- 10.ECM (Engine Control Module DME/DDE)
- 11.IC (Instrument Cluster INSTR)
- 12.ZBE/CON (Controller)
- 13.FRM (Footwell Module)
- 14.AC (Air Conditioning IHKA)

## Additional Request Sheet

The below document should be submitted to the assessing department with the applicable photos and supporting documents. Please allow the the Delow accument should be submitted to the assessing department with the applicable photos and supporting documents. Please allow the assessing department 48 hours to process the request, if no feedback is provided within the given time please contact the assessing department

No additional, unseen damages or deviation from the attached RCS will be allowed unless approved by the insurer. Work in progress and photos must he submitted for approval to the claims department at assessing@primaryasset.co.za

imaryasset.co	iza aniess approved by the insuri
Cell Number:	
wa womber:	
epairer:	Motor Accident Group
C	Cell Number: ox Number:

INSE PILON PEAS	PARTIE PARTIE MATERIA		(D) 13. A (O) 9	адурар Гацу	(Feb.)	in the air	Flam.
- CO 00 00 15	R 275		R	R	P12750		
	R	R	R	R	R	-	WERGE SE ATTACLIED
	R	R	R	R	R		REASE SE ATTROJED  GUSTE FROM LOCKEMITE TO SUPPLY & PROGRAMM  KEYE ON CAP
	R	R	R	R	R		10 STPM & PROGRAMM
	R	R	R	R	R		KENS ON CAS
	R	R	R	R	R		
	R	R	R	R	R		
	R	R	R	R	R		
	P	R	R	R	R		
	R	.R	R	R	R		
	P	R	R	R	R		
	R	R	R	R	R		
	R	R	R	R	R		
	R	R	R	R	R		
	R	R	R	R	R		
	D	R	R	R	R		
Ports		R	R	R	R		

Total Ports	RIAM
Total Labour	"D750
Total SAR	P
Total Paint	R
Sub-Total	P
VAT	R
TOTAL	81276

Please credit balance if the initial approved amount was not deducted on your price difference.

Repairer MAS

Assessor

agreed w.o.p

Prime Meridian Direct (Pty) Ltd. Directors: R. Fihrer, C. Multin and D. Malthews, Registration No: 2004/032998-9 VAT Reg No.: 4720216763, FSP41040, Prime Meridian House, Bryanston Gate, 170 Curzon Rd, Bryanston 2191 PosiNet Suite 430, Private Bag XS1, Bryanston, 2021.





### **Motor Accident Group Notification Of Differences**

REPAIRER:

Motor Accident Group

WBA3D36070NN69387

VIN: CLAIM NO:

CL100743171

VEHICLE MAKE: VEHICLE REG:

BMW 320D CN18NVGP

ASSESSOR:

JUAN LABUSCHAGNE

ASSESSOR TEL:

INSURANCE: DONE BY:

WIP - Zubair 0112345678

TELEPHONE NO: ASSESSOR MAIL:

ASSESSING@PRIMARYASSEST.CO.ZA

REF: ML1001589
Email: add@motoraccidentgroup.co.za

#	Desgription	Cour .	Quantity	Actual Cost	Quoted Cost	Saving	Balai salamati	7
1	MASTER KEY LOCK	New	1	6,375.00	2,087,45	0.00	Additional	
2	LOCKSET CPL	New	1	6,375.00	8,770.21	2,395,21	4,287.55	-
3	BONNET CABLE LEVER	New	1	394.85	309.01		0.00	-
4	BONNET CABLE	New	1	754.33	339.45	0.00	85.84	
5	L/COVER INSTR PANEL	New	1	251.88		0.00	414.88	4
6	R/COVER INSTR PANEL	New	1	251.88	274.15	22,28	0.00	
7	CTR CONSOLE CONTROL	New	1		274.15	22.28	0.00	
8	INSTR PANEL CTR CVR	New	1	4,982.13	5,455.19	473.07	0.00	
9	R/F CTR CONSOLE TRIM	New	- 4	309.55	242.26	0.00	67.29	1
10	CENTRE CONSOLE			1,369.63	1,823.05	453.43	0.00	1
11	R/CTR CONSOLE TRIM	New	1	5,233.64	5,414.63	180.99	0,00	1
12	R/R BACKREST TRIM	New	1	1,135.75	1,312.64	176.89	0.00	1
13	CLIPS	New	1	3,015.11	3,909.75	894.64	0.00	1
		New	1	375.00	300.00	0.00	75.00	f
14	DIAGNOSTICS	Inhouse	1	9//.50 ,500 50	0.00	0.00	1 EC2 EA	977
15	PROGRAM UNITS	Inhouse	1	77.503,568.50	0.00	0.00	4,548,64	977
16	POLISH CPL	Inhouse	1	502,50	9100			1911
17	VALET	Inhouse	1	5-60-00	0.00	0.00	502.50	
18	covid as per sla	Convid 19	1	43 64	0.00	0.00		ľ
fotal	, , , , , , , , , , , , , , , , , , , ,			75 544 02	20 E11 04		137,55	l
					30,511.94	4,618.77		

MB: PLEASE EMAIL BACK TO M.A.G TO COMMENCE AT add@motoraccidentgroup.co.za

32778.75

6810.56

Signature:.....

Total additional incl vat: R2191.79

Agreed 27/01/2021
SJacobs

### **Additional Request Sheet**

The below document should be submitted to the assessing department with the applicable photos and supporting documents. Please allow the assessing department 48 hours to process the request, if no feedback is provided within the given time please contact the assessing department directly on 011 745 7800.

No additional, unseen damages or deviation from the attached RCS will be allowed unless approved by the insurer. Work in progress and photos must be submitted for approval to the claims department at assessing@primaryasset.co.za

Motor Assessor: Office Number: Email:		Cell Number: Fax Number:	the week has provided by the high of the homography
Date of Request:	CL100743171	Repairer:	Motor Accident Group
Insured:	Mr KH Malesela	•	Moest recognic gloup
Vehicle Type:	2013 BMW 320D SPORT LINE (F	F30) (05037158)	

TESCENTION.	PETUEN P	Long car Corat	COST	Call	19704 AMOUNT	ATPHIBLED FORGITALD	6.450%
ACEUTS ACEUTS	<b>Coles</b>	.02	В	D D		<del> </del>	AS HE HYTINGHED THE
No. of the same of	R	R	R	8	R		+Drive
Declined - vehicle	is out of	warran	tya	3	R	holppank speet top claim as me super	
xxx / secondhand and should be red	parts sh	ould be	quoted	R	R	androperat pears, weeks a second per to the tea	S VM M. Watershoot "are validated by
and should be real	in ected to a met	R	R	R	440.6.	The second secon	
}	R	, R	R	R	R	et Min. etc.	6 to the second of the second
Please contact to c Edgar info@vanos	obtain qu acd.co.:	iote for zą, edgi	repairs ar@van	osacd.	co.za	n = 9. Shuku Ri Shid seesed	Total Comment
. The	R	R R	8	R	R	proposes, for single and by the single specific	The state of the s
		D 1	P	Miles de la la la managaman de la companya de la co	white year of reason to the	the removals, substituting	
		1 1	44	R	R		E E
	d to the second	R	R	R	R	10 M TAV Subst of Alexanders	\$ . Maria
	2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	R	R	R	R R R R R R R R R R R R	"O' Mills of r) in Alequeses."  The large scripts — "O's others"	\$
	Section 1997 to the second section of the section	R		consesses us. q., man	R R	10 Mills of a Absolute  A Resource  A Section of the Section of th	
	E	R	R	consesses us. q., man	R R	The first control of the second of the first control of the first contro	The state of the s
	E. Santage of the san	R R R	R	R R	R R R	The first service of the service of	
	E CRAMA	R R R	R	R R R	R R R R		The state of the s
	5	R R R R	R R R	R R R R R R R R R R R R R R R R R R R	R R R R R	Charles on the same of the sam	Section 1 Sectio

Total Parts	
Total Labour	· · · · · · · · · · · · · · · · · · ·
Total S & A	2
Total Point	
Sub-7otal	
VAT	
1 44	15 83 P

Vehicle Reg:

CV18NVGP

Repairer Assessor

Prime Meridian Direct (Pty) Ltd. Directors: R. Fihrer, C. Mullin and D. Marthews. Registration No. 2004/232998/07, VAT Reg No.: 4720216763, FSP41840. Frime Meridian House, Bryanston Gate. 176 Curson Rd, Bryanston, 2191 PostNet Suite 430, Private Bag XS1, Bryanston, 2021.

Your policy is administered by PrimaryAsset Administrative Services (Ptyl Ltd. PrimaryAsset Administrative Services (Ptyl Ltd. PrimaryAsset Administrative Services (Ptyl Ltd. Directors: N. Fernandes and D. Venter. Registration Aumber: 1952/001306/07. VAT Reg No.: 4880179629, FSP3920. Block S, Bryanston Gate Office Park, 81 Homestead Avenue, Bryanston, 2191.

