Lesson 20:

Customizing standard reports



IGSS

Interactive Graphical
SCADA System

YouTube
Broadcast Yourself™

Contents of this lesson




Topics:

- **Create the standard report format**
- **Run the report from Supervise**
- **Customize the report in Excel**
- **Run the customized report using Data to Excel**


Create the report format

1. In Definition, create a new report format called ”Data to Excel Report”.
2. Create a report section called ”Flow Meters”.
   Choose **Set as Default**.
3. Select the three flow gauges – q1, q2, q3 – and drag them into the report section.
4. In the list view, select the three objects and select all check boxes.
5. Click OK and install the configuration.



Run the report in Supervise

1. In Supervise, go to the **User Programs** menu and select **Periodical Report**.
2. Select the appropriate report date.
3. Click **Data to Excel**.
4. Explain what you get by default in the Excel report.



Customize the report in Excel

1. Open the Excel file named **Data to Excel Report.xls** in the configuration's report folder.
   This file is created the first time a user exports this report format to Excel.
   The file thus becomes the template for all Excel reports generated for this report format.
2. Go to the **Detail Report** sheet.
3. Create a new column called "q4 – Total Flow".
4. Create a sum for q1 + q2 + q3 for each hour.

q3 Global Average m³/h	q4 Total Flow m³/h
	0,0
0,0	0,0
0,0	0,0
0,0	0,0
0,0	0,0
0,0	0,0
0,0	0,0
0,0	0,0
0,0	0,0
0,0	0,0
44,3	154,2
60,0	160,2
77,9	174,8
67,3	166,5
12,0	115,7
19,0	117,4
33,7	132,1
	0,0
	0,0
	0,0
	0,0
	0,0
	0,0
	0,0
1255,8	3702,9
52,3	154,3
25,6	34,5

Create the pie chart for q4 - Total flow



Chart for q4 - Total flow

1. Select the total values for q1, q2 and q3.
2. Go to insert and create a pie chart.
3. Go to the **Layout** tab. Select **Chart Title** > **Above Chart**. Type ”q4 – Total flow”.
4. Right-click the legend and choose **Select Data**.
5. Select the three cells q1, q2, q3.

Create the scatter chart for q1, q2, q3




Detailed graph for flows

1. Select all hours + values for q1, q2 and q3.
2. Go to the **Insert** tab and create a pie chart.
3. Go to the **Layout** tab. Select **Chart Title** > **Above Chart**. Type ”Detailed graph for flows”.
4. Right-click the legend and choose **Select Data**.
5. Select **Series 1**, click **Edit**, choose q1.
6. Repeat step 5 for q2 and q3.

Edit the VBA code to avoid overwriting of data

Make sure that VBA macros are enabled.


1. Enable the **Developer** tab in Excel 2007 in the **Options** dialog box.
2. Go to the **Developer** tab.
3. Click the **Macro Security** button.
4. Under **Macro Settings**, select the last option **Enable all macros**.
5. Under Developer Macro Settings, select the **Trust access to the VBA ….** Check box.



Edit the VBA code


1. Click the **Macros** button.
2. Select **MakeDetailReport**.
3. Click **Edit**.
4. Double-click **ThisWorkbook**.
5. Find the line beginning with: **”ClearSheet ReportSheet”**.
6. Insert a single quotation mark **'** as the first character in the line.
7. Close the macros window and close Excel.

By default, IGSS will clear all data in the Excel workbook. But we want to keep the new column and charts that we created in the Data to Excel template.



Run the customized report

1. In Supervise, go to the **User Programs** menu and select **Periodical Report**.
2. Select the appropriate report date.
3. Click **Data to Excel**.
4. Explain what you get by default in the Excel report.



Try it yourself ...



Please do
Exercise xx: <Title>