Projects 5 and 13

GOAL:

Create a runtime screen which shows the usage of the system to include hours of operation, a cycle count of backwashes and reset buttons for both hourmeter and cycle counter.

SUMMARY:

Many systems require routine maintenance / service to be performed on a periodic basis, and that basis USUALLY depends upon runtime rather than simple calendar time. In our system, for example, we have a media filter which we backwash regularly, but even still… eventually we're going to have to replace the media.

Another consideration is warranty. Many systems such as this are warranted by the manufacturer to operate without failure for a certain number of hours. For reasons such as these, having a screen to monitor our system usage is usually a required component of any complete HMI application

TAG USAGE:

N7:8	BACKWASH_COUNT	Backwash Cycle Count
N7:11	HOURMETER_HRS	Hourmeter Hours
N7:12	HOURMETER_KHRS	Hourmeter Hours (x1000)
N7:10	HOURMETER_MINS	Hourmeter Minutes
N7:9	HOURMETER_SECS	Hourmeter Minutes
B3:6/3	RESET_BW_COUNT_PB	Reset Backwash Cycle Count Pushbutton from HMI
B3:6/9	RESET_HOURMETER_PB	Reset Hourmeter Pushbutton from HMI