Assembly Field Values

**Machine Code** 

			imm <sub>12,10:5</sub>				,	op	imm <sub>12,10:</sub>	rs2	rs1	funct3	imm <sub>4:1,11</sub>	
bne s8, bne x24,	<b>s9</b> ,	L1 L1	1100 101	25	24	1	0010 0	99	1100 101	11001	11000	001	0010 0	11
	/		7 bits	5 bits	5 bits	3 bits	5 bits	7 bits	7 bits	5 bits	5 bits	3 bits	5 bits	

•

```
mm<sub>4:1,11</sub> op

0010 0 110 0011

5 bits 7 bits (0xCB9C1263)
```