	Machine Code						Field Values						Assembly
	funct7	rs2	rs1	funct3	rd	ор	funct7	rs2	rs1	funct3	rd	ор	
(0x41FE83B3)	0100 000	11111	11101	000	00111	011 0011	32	31	29	0	7	51	sub x7, x29,x31 sub t2, t4, t6
	7 bits	5 bits	5 bits	3 bits	5 bits	7 bits	7 bits	5 bits	5 bits	3 bits	5 bits	7 bits	3 340 62, 64, 60
	imm _{11:0}		rs1	funct3	rd	ор	imm _{11:0}		rs1	funct3	rd	op	
(0xFDA48293)	1111 1101 1010		01001	000	00101 001 0011		-38		9	0	5	19	addi x5, x9, -38 addi t0, s1, -38
	12 bit	bits 5 bits 3 bits 5 bits		5 bits	7 bits 12 b		s	5 bits 3 bits	3 bits	5 bits	7 bits	3 addi co, 31, 30	