Floating point numbers

	rioding point numbers			
	0 10000001	111 1100 0000 0000 0000 0000		
	0 01111100	100 0000 0000 0000 0000 0000		
	Exponent	Fraction		
Step 1	10000001	111 1100 0000 0000 0000 0000		
	01111100	100 0000 0000 0000 0000 0000		
	10000001	1.111 1100 0000 0000 0000 0000		
Step 2	01111100	1.100 0000 0000 0000 0000 0000		
	01111100	1.100 0000 0000 0000 0000 0000		
Step 3	10000001	1.111 1100 0000 0000 0000 0000		
	- 01111100	1.100 0000 0000 0000 0000 0000		
101 (shift amount)				
Step 4	10000001	1.111 1100 0000 0000 0000 0000		
	10000001	0.000 0110 0000 0000 0000 0000	00000	
Step 5	10000001	1.111 1100 0000 0000 0000 0000		
	10000001 +	0.000 0110 0000 0000 0000 0000		
		10.000 0010 0000 0000 0000 0000		
Step 6		10.000 0010 0000 0000 0000 0000 3	>> 1	
	10000010	1.000 0001 0000 0000 0000 0000		
Step 7	(No Rounding	Necessary)		
Step 8	0 10000010	000 0001 0000 0000 0000 0000		