A	ssembly	Field Values					Machine Code				
		imm _{11:0}	rs1	funct3	rd	ор	imm _{11:0}	rs1	funct3	rd	ор

		111111111111111111111111111111111111111		idiloto		٠,
lw	t3, -36(s4) x28, -36(x20)	-36	20	2	28	3
lw	x20, -30(X2U)	12 bits	5 bits	3 bits	5 bits	7 bits

IIIIII1 _{11:0}	ISI	luncis	Iu	op	IIIIII _{11:0}	ISI	luncis	Iu	op
-36	20	2	28	3	1111 1101 1100	10100	010	11100	000 0011
12 bits	5 bits	3 bits	5 bits	7 bits	12 bits	5 bits	3 bits	5 bits	7 bits

op 00 0011 (0xFDCA2E03) 7 bits