Assembly	Field Values					Machine Code				
	imm _{11:0}	rs1	funct3	rd	ор	imm _{11:0}	rs1	funct3	rd	ор
csrrs x7, mcause, x3	0x342	3	2	7	115	0011 0100 0010	00011	010	00111	111 0011
	12 bits	5 bits	3 bits	5 bits	7 bits	12 bits	5 bits	3 bits	5 bits	7 bits

op 111 0011 (0x3421A3F3)

7 bits