2 1 3 PHASE - 9 LEADS - WYE **LINES** CONN. **CONNECTED VOLTS TOGETHER L2** L1 L3 TT\_T T2 Т3 LOW YY T8 T4 T5 T6 **T1 T2** T4 T7-T5 T8-T6 T9 **HIGH T3** В T6 T9 **T3** THIS IS A CAD DRAWING DO NOT MAKE MANUAL CHANGES -confidential- PROPERTY OF
Siemens Energy & Automation, Inc.
Industrial Motor Division — Little Rock, AR 09-27-07 HP FRAME WIRING DIAGRAM Customer VOLTS RPM ΗZ PH P0 # S0 # DRAWN 9.24.07 JRH DATE 51-382-114-501 SHEET Sim. To CHECKED DATE 1 OF 1 DATE

В

Α