EXAMPLE SHIPBUILDERS LTD.

PUNCH LIST - DECK AND ACCOMMODATION (Sheet 1 of 2)

Project: Hull 101 Date: 20.09.2026 Agency: Yard QA

SAMPLE DOCUMENT - fictitious data for demonstration only

SL	SYSTEM	REMARK	RESULT
1	Windlass	Brake lining worn on port wildcat. Replace lining.	UNSAT
2	Mooring Winch	Load test completed at 12 t.	SAT
3	Rescue Boat Davit	Limit switch not operating in the stowed position. Adjust.	UNSAT
4	Liferaft Cradle	Hydrostatic release is past its expiry date. Replace.	UNSAT
5	Accommodation Door	Fire door D-12 does not fully self-close. Adjust the closer.	UNSAT
6	Galley	Exhaust duct fire damper has no position indication.	UNSAT
7	Cabin 106	Insulation gap in way of the cable penetration. Rectify.	UNSAT
8	Navigation Lights	All lights and the panel alarm tested satisfactory.	SAT

EXAMPLE SHIPBUILDERS LTD.

PUNCH LIST - DECK AND ACCOMMODATION (Sheet 2 of 2)

Project: Hull 101 Date: 20.09.2026 Agency: Yard QA

SAMPLE DOCUMENT - fictitious data for demonstration only

SL	SYSTEM	REMARK	RESULT
9	Cargo Deck	Timber sheathing bolts loose at frame 14. Retighten.	UNSAT
10	Fresh Water System	Pressure set pump cycling too often. Check the accumulator.	UNSAT
11	Sewage Plant	Discharge test completed. Certificate to be supplied.	SAT
12	Bridge Wing	Control station cable gland is loose. Retighten and seal.	UNSAT

All open remarks are to be closed before sea trials.

Signed: Yard QA Inspector