


P1 Project Drawing Updates - 10/24/2019

BR-549-A-002


Groove diameter was missing. Also there are 7 (not 6) 0.5 x 45° chamfers.



DETAIL C

BR-549-B-001

Spacing of 8 hole pattern was missing




BR-549-B-003

Volume was incorrect. Should have been 89429 mm³


BR-549-B-001

4 holes were missing hole callouts




BR-549-B-006

Overall height dimension was missing; should be 412



BR-549-C-001

Keyway depth dimension was missing




BR-549-C-002

Mass and volume were incorrect

DRAWN	NAME	DATE	Ferris State University		
DRAWN	BRIAN BRADY	10/16/2019			
CHECKED			TITLE		
APPROVED			DRILL UNIT MAIN ASSEMBLY DETAILS BALL SCREW SUPPORT BRACKET		
MATERIAL	STEEL 1020	VOLUME	SIZE C	DWG NO. BR-549-C-002	REV.
		625418 mm ³	SCALE 1:2	WEIGHT 4.922 kg	SHEET 5 of 20


BR-549-C-003

Chamfer dimension was missing




BR-549-C-011

Missing radius dimension



BR-549-B-006


Missing dimension



And incorrect volume; should be 1369576 mm³

BR-549-B-001

Added TYP to 30 dimension as shown below



BR-549-B-010

Added TYP to 30 dimension as shown below

