



















ZONE 1: AC MAINS & POWER SUPPLIES







ZONE 2: MAIN CONTROLLER & FIELD I/O







ZONE 3: MOTION CO-PROCESSOR (STM32)



ZONE 4: STEPPER MOTOR DRIVERS



ZONE 5: ACTUATORS & SENSORS



SHIELDED SENSOR-SIGNAL-HIGHWAY (D10-D110) ROUTED VIA BASE-RACEWAY