## PIVlab

List of keyboard shortcuts. Print it, pin it, be happy.

CTRL + N	new session / load image data
CTRL + E	exclusions / region of interest / mask
CTRL + I	image pre-processing
CTRL + S	PIV settings
CTRL + A	analyze current frame / all frames
CTRL + V	vector validation
CTRL + Z	calibration
CTRL + D	derive parameters / modify data
CTRL + M	modify plot appearance
CTRL + P	extract parameters from poly-line / circle
CTRL + Q	extract parameters from area
CTRL + T	measure distance and angle / markers
CTRL + B	statistics
CTRL + G	synthetic particle image generation
CTRL + H	help / getting started