


P_O [$C_r=1480\mu F$, $R_L=14.00\Omega$, rpm=100] (Y)

Power [mW]



— P(FWR1)
— P(FWR2)