


P_O [$C_r=1480\mu F$, $C_L=630.0\mu F$, rpm=100] (FWR-Y)

Power [mW]



— P(FWR1)
— P(FWR2)