



PSR | BSI Colombia S.A.

1/06/2026	95002593	DC00	22
1/06/2026	95002593	RC00	7

SUPERV LUIS AGUIRRE WTM-Vanti TRABAJO: 1/06/2026 TECNICO: 95002593 JOSE APARICIO

MALLA SECTOR		SECC DIRECCION		CUENTA	ODS	ORDEN	MEDIDOR	DESCRIPCION AVISO	TOTAL: 29
178	BUENOS AIRES	008	TV 18I 76 SUR 87	64347151	W	41961578 . RC00	CREA 5007111-723274 .	* 31/05/2026 11:20	
178	BUENOS AIRES	009	CL 75A SUR 18A 79 01 00002	63033588	W	101358436 . DC00	CREA 5007119-3550641 .		
178	BUENOS AIRES	009	KR 18B 74C SUR 9 00001	61201902	W	101370931 . DC00	CREA 5067199-61130 .		
178	BUENOS AIRES	009	KR 18B BIS A 73A SUR 30 02	60940477	W	101368971 . DC00	CREA 5037199-27649 .		
178	BUENOS AIRES	010	CL 73A SUR 18G 54 01	62597645	W	101372000 . DC00	CREA 5007109-496180 .		
178	BUENOS AIRES	010	KR 18K 76A SUR 36	62220697	W	41961307 . RC00	CREA 5007107-353742 .	* 31/05/2026 09:48	
178	BUENOS AIRES	013	KR 18B 78 SUR 27	62848699	W	101373406 . DC00	CREA 5007107-296710 .		
178	BUENOS AIRES	022	CL 74 SUR 17F 15 T05 00903	63877548	W	41961036 . RC00	CREA 007520220010017152 .	* 31/05/2026 07:07	
178	BUENOS AIRES	022	CL 78C SUR 17J 20 00001	61815616	W	41961126 . RC00	CREA 5097103-126277 .	* 31/05/2026 08:39	
178	BUENOS AIRES	022	KR 17F 77A SUR 11 T01 00204	64480139	W	101334361 . DC00	CREA 5007117-3282306 .		
178	BUENOS AIRES	022	KR 17F 77A SUR 11 T01 00304	63108092	W	101326096 . DC00	CREA 5007117-3282303 .		
178	BUENOS AIRES	022	KR 17F 77A SUR 11 T01 00601	63098819	W	101374140 . DC00	CREA 5007117-3282299 .		
178	BUENOS AIRES	022	KR 17F 77A SUR 11 T02 00503	63098926	W	101373506 . DC00	CREA 5007117-3295482 .		
178	BUENOS AIRES	022	KR 17F 77A SUR 11 T02 00604	64469467	W	101334334 . DC00	CREA 5007117-3282177 .		
178	BUENOS AIRES	022	KR 17F 77A SUR 11 T03 00202	62989508	W	101374082 . DC00	CREA 5007116-3252958 .		
178	BUENOS AIRES	022	KR 17F 77A SUR 11 T05 00302	62956450	W	101325036 . DC00	CREA 5007116-3241151 .		
178	BUENOS AIRES	022	KR 17F 77A SUR 11 T05 00303	62960081	W	101374381 . DC00	CREA 5007116-3241156 .		
178	BUENOS AIRES	022	KR 17F 77A SUR 11 T06 00201	62944206	W	101373826 . DC00	CREA 5007116-3239982 .		
178	BUENOS AIRES	022	KR 17F 77A SUR 11 T06 00403	62964783	W	101334304 . DC00	CREA 5007116-3255214 .		
178	BUENOS AIRES	022	KR 17F 77A SUR 11 T08 00203	62946243	W	101335932 . DC00	CREA 5007116-3255086 .		
178	BUENOS AIRES	022	KR 17F 77A SUR 11 T09 00204	62887939	W	101374204 . DC00	CREA 5007116-3231203 .		
178	BUENOS AIRES	022	KR 17F 77A SUR 11 T10 00303	62889910	W	101325059 . DC00	CREA 5007116-3230496 .		
178	BUENOS AIRES	022	KR 17F 77A SUR 11 T10 00504	62891589	W	101361183 . DC00	CREA 5007116-3228965 .		
178	BUENOS AIRES	022	KR 17F 77A SUR 11 T10 00603	62896356	W	41911905 . RC00	REAC 5007116-3230490 .	* 31/05/2026 14:47	
178	BUENOS AIRES	022	KR 17F 77A SUR 11 T10 00604	62889544	W	101373941 . DC00	CREA 5007116-3230488 .		
178	BUENOS AIRES	022	KR 17K 78 SUR 4 01	62679541	W	41962302 . RC00	CREA 5007112-765784 .	* 31/05/2026 16:42	
178	BUENOS AIRES	022	KR 17L 74 SUR 12 00001	62035993	W	41962475 . RC00	CREA 5057101-182284 .	* 31/05/2026 20:11	
178	BUENOS AIRES	022	KR 17N 75 SUR 69 01 00101	63886214	W	101374496 . DC00	CREA 007120230003902784 .		
178	EL TESORITO	014	CL 80 SUR 19 54 01 00001	64254487	W	101296033 . DC00	CREA 007120240003985423 .		