



PSR | BSI Colombia S.A.

1/06/2026	95004543	DC00	12
1/06/2026	95004543	RC00	17

SUPERV SALOMON GUERRERO WTM-Vanti TRABAJO: 1/06/2026 TECNICO: 95004543 YESID CUERVO

MALLA SECTOR		SECC DIRECCION		CUENTA	ODS	ORDEN	MEDIDOR	DESCRIPCION AVISO	TOTAL: 29
110	TECHO	034	DG 3 73B 79 01	61066982	W	101384443 . DC00	CREA 5087196-49827 .		
110	TECHO	034	DG 3 73C 6 C50	62065071	W	101384433 . DC00	CREA 5097106-173289 .		
110	TECHO	034	DG 5A 73B 5 01	61049407	W	101346932 . DC00	CREA 5087196-62652 .		
110	TECHO	034	DG 5A 73C 77 00001	61955674	W	41962347 . RC00	CREA 5087104-23828 .	* 31/05/2026 18:03	
110	TECHO	034	KR 73 3 87 01	60913110	W	41962042 . RC00	CREA 5087196-49170 .	* 31/05/2026 14:35	
110	TECHO	034	KR 74 1 3 01	60763941	W	101382662 . DC00	CREA 5087196-49020 .		
110	TECHO	034	KR 75 1 52 00001	61089891	W	101381588 . DC00	CREA 5087196-49814 .		
110	TECHO	036	CL 1 SUR 72 32 01	61076205	W	41962031 . RC00	CREA 5017118-3463231 .	* 31/05/2026 14:35	
110	TECHO	036	CL 1A SUR 72B 56 01	60769011	W	41962120 . RC00	CREA 5087196-49310 .	* 31/05/2026 14:54	
110	TECHO	036	CL 1A SUR 72C 14 01	60620835	W	41962397 . RC00	CREA 5087196-76386 .	* 31/05/2026 18:34	
110	TECHO	036	CL 2 BIS 72B 77	60817243	W	41961806 . RC00	CREA 5157198-66685 .	* 31/05/2026 12:34	
110	TECHO	036	CL 2 SUR 72 48 01	64429734	W	41962222 . RC00	CREA 5087196-63312 .	* 31/05/2026 15:49	
110	TECHO	036	CL 2A 72 36 I03 00101	61492647	W	101382845 . DC00	CREA 5087196-139228 .		
110	TECHO	036	CL 2A 72 36 I06 00301	60846521	W	101382586 . DC00	CREA 5087196-49355 .		
110	TECHO	036	CL 2A SUR 72 82 01	60973539	W	41961170 . RC00	CREA 5087196-76364 .	* 31/05/2026 09:06	
110	TECHO	036	CL 2A SUR 72B 26 01	61145285	W	41961635 . RC00	CREA 5087196-48106 .	* 31/05/2026 11:34	
110	TECHO	036	CL 2A SUR 72B 48 00001	61963014	W	41962265 . RC00	CREA 5097103-178585 .	* 31/05/2026 15:59	
110	TECHO	036	KR 72B 1 SUR 36 01	60792364	W	41961701 . RC00	CREA 5087196-53146 .	* 31/05/2026 11:45	
110	TECHO	036	KR 73 1 SUR 25 01	61112123	W	41962174 . RC00	CREA 5077198-147012 .	* 31/05/2026 15:36	
110	TECHO	036	KR 73A 0 4 01	60758228	W	41961492 . RC00	CREA 5087196-77258 .	* 31/05/2026 11:11	
110	TECHO	037	CL 1 73B 55 02	60655426	W	41961955 . RC00	CREA 5087196-15942 .	* 31/05/2026 13:16	
110	TECHO	037	CL 26 SUR 72C 30 03	60869706	W	101335309 . DC00	CREA 5097197-221415 .		
110	TECHO	037	CL 2A SUR 73B 52 00302	61074415	W	41961592 . RC00	CREA 5087196-23333 .	* 31/05/2026 11:31	
110	TECHO	037	CL 2A SUR 73B 52 01 00002	61076190	W	41961254 . RC00	CREA 5007117-3365388 .	* 31/05/2026 09:55	
110	TECHO	037	CL 5A SUR 73C 23 B0B 00202	60810979	W	101384891 . DC00	CREA 5077198-66119 .		
110	TECHO	037	CL 5A SUR 73C 23 B0C 00502	60810806	W	101385342 . DC00	CREA 5077198-104114 .		
110	TECHO	037	CL 5A SUR 73C 23 B0E 00302	60801756	W	101382714 . DC00	CREA 5077198-90170 .		
110	TECHO	037	KR 72D 2A SUR 35 00001	61318671	W	41962082 . RC00	CREA 5027100-117580 .	* 31/05/2026 14:44	
110	TECHO	038	CL 26 SUR 73F 66 00206	61193136	W	101381695 . DC00	CREA 5087196-55776 .		