



PSR | BSI Colombia S.A.

SUPERV SALOMON GUERREROWTM-VantiTRABAJO: 1/06/2026TECNICO: 95003334JUNGMANN DIAZ

MALLA SECTOR		SECC DIRECCION		CUENTA	ODS	ORDEN	MEDIDOR	DESCRIPCION AVISO	TOTAL: 32
110	TECHO	038	KR 73 1 SUR 60 B60 I09 00402	61226590	W	101382427 . DC00	CREA	5087196-47977 .	
110	TECHO	038	KR 73 1 SUR 60 B60 I11 00502	61232895	W	101381905 . DC00	CREA	5087196-48768 .	
110	TECHO	038	KR 73 1 SUR 60 B62 I17 00302	60988733	W	101384436 . DC00	CREA	5087196-62814 .	
110	TECHO	038	KR 73 1 SUR 60 I03 00502	60891319	W	101381428 . DC00	CREA	5007114-1043755 .	
110	TECHO	038	KR 73F 6 SUR 41 B0B 04 00410	61152817	W	101384293 . DC00	CREA	5087196-76605 .	
110	TECHO	038	KR 73F 6 SUR 41 B0B 12 00302	61234438	W	101349664 . DC00	CREA	5087196-77511 .	
110	TECHO	038	KR 74 0 31 01	61148903	W	101345798 . DC00	CREA	5087196-14805 .	
110	TECHO	038	KR 78 0 70 B65 I07 00502	60727251	W	101382326 . DC00	CREA	5087196-49222 .	
110	TECHO	038	KR 78 0 70 I20 00202	61220889	W	101382086 . DC00	CREA	5087196-55731 .	
110	TECHO	039	KR 78 1 17 B37 I33 00201	62342002	W	101371483 . DC00	CREA	5087196-322507 .	
110	TECHO	039	KR 78 1 17 I07 02 00202	62937101	W	101382565 . DC00	CREA	5007119-3532872 .	
110	TECHO	039	KR 78 1 17 I15 00401	61242243	W	101382611 . DC00	CREA	5087196-52231 .	
110	TECHO	039	KR 78 1 17 I16 00401	60671620	W	101383011 . DC00	CREA	5097197-162488 .	
110	TECHO	039	KR 78 1 17 I20 00401	60828542	W	101383327 . DC00	CREA	5087196-56485 .	
110	TECHO	039	KR 78 1 17 I36 00202	61070163	W	101383171 . DC00	CREA	5097197-104044 .	
110	TECHO	039	KR 78 1 3 I17 00401	60664245	W	101382279 . DC00	CREA	5087196-106953 .	
110	TECHO	039	KR 78 1 3 I19 B45 00502	62365299	W	101381704 . DC00	CREA	5007113-916235 .	
110	TECHO	039	KR 78 1 3 I21 00401	63082697	W	101385191 . DC00	CREA	5017118-3478477 .	
110	TECHO	039	KR 78 1 5 L01 00001	63566972	W	101382557 . DC00	CREA	5037199-77960 .	
110	TECHO	039	KR 78 6 SUR 61 I11 B56 19 00501	61399076	W	101383873 . DC00	CREA	5037101-37022 .	
110	TECHO	039	KR 78 6 SUR 61 I15 00401	60666424	W	101381991 . DC00	CREA	5087196-56307 .	
110	TECHO	039	KR 78B 6 SUR 60 00502	64196189	W	101384831 Pri DC00	CREA	010720240003967621 .	
110	TECHO	040	KR 75 36A SUR 50 I13 B35 14 00301	61086394	W	101384697 . DC00	CREA	5087196-50269 .	
110	TECHO	040	KR 75 36A SUR 50 I13 I04 00102	62002866	W	101382405 . DC00	CREA	5087104-172709 .	
110	TECHO	040	KR 78B 1 5 B23 I02 05 00502	62221003	W	101384517 . DC00	CREA	5097106-237792 .	
110	TECHO	040	KR 78B 1 5 B24 I06 00401	63930352	W	101385913 . DC00	CREA	5007114-1031400 .	
110	TECHO	040	KR 78B 1 5 B27 I21 00401	61129591	W	101383633 . DC00	CREA	5067199-138015 .	
110	TECHO	040	KR 78B 1 5 B28 I25 00502	63784524	W	101382953 . DC00	CREA	5087196-323134 .	
110	TECHO	040	KR 78B 1 5 I02 B28 27 00301	61984643	W	101385204 . DC00	CREA	5067105-500014125 .	
110	TECHO	040	KR 78B 1 5 I17 00202	61193470	W	101383634 . DC00	CREA	5087196-57394 .	
110	TECHO	040	KR 78F 0 33 B05 I24 00501	62438438	W	101383714 . DC00	CREA	5157198-60704 .	
110	TECHO	040	KR 78F 0 33 I04 00101	60887672	W	101335292 . DC00	CREA	5087196-76125 .	