



PSR | BSI Colombia S.A.

1/06/2026	95006298	DC00	19
1/06/2026	95006298	RC00	11

SUPERV JHON GUTIERREZ WTM-Vanti TRABAJO: 1/06/2026 TECNICO: 95006298 BRAYAN FERRER

MALLA SECTOR		SECC DIRECCION		CUENTA	ODS	ORDEN	MEDIDOR	DESCRIPCION AVISO	TOTAL: 30
110	TECHO	032	CL 4 72A 43 02	60867014	W	101382318 . DC00	CREA 5087196-49815 .		
110	TECHO	032	CL 5A 72A 27 00504	61044256	W	101381755 . DC00	CREA 5087196-49734 .		
110	TECHO	032	KR 72 BIS 4 51 01	61010641	W	41961440 . RC00	CREA 007120250004066800 .	* 31/05/2026 10:41	
110	TECHO	032	KR 72A 2A 24 01	60999560	W	41961494 . RC00	CREA 5087196-104879 .	* 31/05/2026 11:13	
110	TECHO	032	KR 72A 3A 4 01	60613353	W	41962101 . RC00	CREA 5087196-53783 .	* 31/05/2026 14:44	
110	TECHO	032	KR 72A 4 44 01	61008917	W	41962427 . RC00	CREA 5087196-140833 .	* 31/05/2026 19:32	
110	TECHO	032	KR 72B 4 32 01	60887611	W	41962166 . RC00	CREA 5087196-49811 .	* 31/05/2026 15:24	
110	TECHO	032	KR 72B 4 37 01	61014993	W	41962247 . RC00	CREA 5087196-66848 .	* 31/05/2026 16:16	
110	TECHO	032	KR 72B 5B 90 B01 00402	60720315	W	101383986 . DC00	CREA 5167199-89570 .		
110	TECHO	032	KR 72B 5B 90 B03 00110	60827286	W	101382273 . DC00	CREA 5087196-154455 .		
110	TECHO	032	KR 72B 5B 90 B07 00428	60758263	W	101382367 . DC00	CREA 5087196-19986 .		
110	TECHO	032	KR 72B 5B 90 I02 00407	61338571	W	101384654 . DC00	CREA 5167199-100982 .		
110	TECHO	032	KR 72B BIS 2A 45 01 00001	61129274	W	41961711 . RC00	CREA 5167199-107463 .	* 31/05/2026 11:51	
110	TECHO	032	KR 72C 3A 4 01	62754229	W	41961472 . RC00	CREA 5087196-139098 .	* 31/05/2026 11:09	
110	TECHO	032	KR 72C 3B 47	61703281	W	41961837 . RC00	CREA 5037199-26808 .	* 31/05/2026 12:47	
110	TECHO	033	CL 26 SUR 78H 22 01 00002	63976411	W	101386080 . DC00	CREA 5028001-856465 .		
110	TECHO	033	CL 26 SUR 78H 30 B18 B10 38 00301	62430272	W	101383711 . DC00	CREA 5087196-51356 .		
110	TECHO	033	CL 26 SUR 78H 30 I04 00301	63749070	W	101382356 . DC00	CREA 007120210003792339 .		
110	TECHO	033	CL 26 SUR 78H 70 B0A 00403	60926771	W	101385334 . DC00	CREA 5087196-337535 .		
110	TECHO	033	CL 33 SUR 77A 34 B19 I12 00401	60607927	W	101383678 . DC00	CREA 5087196-175493 .		
110	TECHO	033	CL 33 SUR 77A 34 B22 I25 00301	61040601	W	101383648 . DC00	CREA 5087196-52278 .		
110	TECHO	033	CL 33 SUR 77A 34 B22 I27 00202	60861506	W	101384087 . DC00	CREA 5087196-54235 .		
110	TECHO	033	KR 78F 0 25 01 00002	62519886	W	101382972 . DC00	CREA 5017110-633469 .		
110	TECHO	033	KR 78F 0 33 B03 I12 00202	61106473	W	101382549 . DC00	CREA 5077198-386262 .		
110	TECHO	033	KR 78F 0 33 B20 B17 07 00502	61249891	W	101384133 . DC00	CREA 5087196-66594 .		
110	TECHO	033	KR 78F 0 33 I11 B18 00401	61282786	W	101383291 . DC00	CREA 5007119-3583827 .		
110	TECHO	034	CL 2 73B 39 01	62231221	W	41962567 . RC00	CREA 5007109-512815 .	01/06/2026 07:29	
110	TECHO	034	CL 2 73B 65 01	60851919	W	41962056 . RC00	CREA 5087196-29387 .	* 31/05/2026 14:35	
110	TECHO	034	CL 2A BIS 73A 10 01	60674499	W	101383361 . DC00	CREA 5087196-30695 .		
110	TECHO	034	DG 3 73B 74	61746495	W	101383180 . DC00	CREA 000005187101267986 .		