



PSR | BSI Colombia S.A.

1/06/2026	95011790	DC00	10
1/06/2026	95011790	RC00	11
1/06/2026	95011790	ZVCL	3

SUPERV JHON GUTIERREZ WTM-Vanti TRABAJO: 1/06/2026 TECNICO: 95011790 BRANDON ROJAS

MALLA SECTOR		SECC DIRECCION		CUENTA	ODS	ORDEN	MEDIDOR	DESCRIPCION AVISO	TOTAL: 24
172	SAN LUIS	006	KR 100 15A 93 I06 C11	61999910	W	41962753 . RC00	CREA 5057101-189527 .		01/06/2026 16:36
172	SAN LUIS	006	KR 100 15A 93 I15 C20 00001	61425755	W	101379746 Pri DC00	CREA 5107104-60618 .		
172	ZONA FRANCA	005	KR 112A 15D 33 01	61123999	W	101335390 . DC00	CREA 5067199-58975 .		
174	CONDADO DE CAS	009	KR 80 BIS 7A 15 T03 00402	62405393	W	101379808 . DC00	CREA 5007111-704945 .		
174	EL CASTILLO	050	DG 3 83 2 T01 00403	62044449	W	69175354 . ZVCL	CREA 5007111-720170	Visita Suspension por error	* 30/05/2026 11:53
174	EL CASTILLO	050	DG 3 83 2 T04 01005	62115746	W	69175333 . ZVCL	CREA 5007112-800329	Visita Suspension por error	* 30/05/2026 11:31
174	EL TINTAL	019	KR 80F 8D 44 00501	64185817	W	101275757 . DC00	CREA 5127101-6554554 .		
174	EL TINTAL	036	AK 86 10 50 T03 L5A 00304	64213128	W	101298202 . DC00	CREA 007120250004046258 .		
174	EL TINTAL	036	AK 86 10 50 T03 L5A 00408	64213143	W	101298153 . DC00	CREA 007120240004033414 .		
174	EL TINTAL	036	AK 86 10 50 T03 L5A 00705	64213173	W	101298071 . DC00	CREA 007120240004033307 .		
174	EL TINTAL	036	AK 86 10 50 T04 L5A 00903	64213415	W	101298367 . DC00	CREA 009520240000029423 .		
174	EL TINTAL	036	CL 10B 81F 20 T02 01611	62994119	W	41962564 . RC00	CREA 5007218-3517426 .		01/06/2026 07:11
174	RINCON DE LOS AN	004	KR 75 6B 70 I12 00504	60926481	W	69177211 . ZVCL	CREA 007120250004128039	Visita validacion lectura	* 30/05/2026 16:13
174	VILLA ALSACIA	018	KR 73B 8 8 00002	61976955	W	101335691 . DC00	CREA 010420250004041368 .		
174	VILLA ALSACIA	019	CL 8A 78 78	61942961	W	41962188 . RC00	CREA 5097106-171344 .		* 31/05/2026 15:19
182	NUEVA CASTILLA	013	KR 90A 8 67 T04 00729	63461870	W	41962640 . RC00	CREA 007120210003761189 .		01/06/2026 09:20
182	NUEVA CASTILLA	013	KR 92 8 18 T11 00539	62313575	W	101285983 . DC00	CREA 5007112-801034 .		
182	NUEVA CASTILLA	019	AK 86 8B 23 T01 01103	64449419	W	41960980 . RC00	CREA 007120250004124553 .		* 31/05/2026 07:12
182	TINTALA	004	KR 88 6A 99 I16 00203	61168930	W	41958672 . RC00	CREA 5097197-174769 .		* 30/05/2026 06:23
182	TINTALA	007	KR 90C 6A 67 C17 00001	61497649	W	41958856 . RC00	CREA 5057101-164010 .		* 30/05/2026 07:49
182	TINTALA	014	CL 7 92A 56 274 00001	62226606	W	41960329 . RC00	CREA 5017110-586708 .		* 30/05/2026 15:19
182	TINTALA	014	CL 7 94 78 230 00001	61988604	W	41960692 . RC00	CREA 5057105-83890 .		* 30/05/2026 19:25
182	TINTALA	022	CL 6 BIS A 90A 80 T25 00201	61990605	W	41959429 . RC00	CREA 5017118-3474916 .		* 30/05/2026 10:22
182	TINTALA	022	KR 93D 6 80 T03 00603	62047365	W	41960902 . RC00	CREA 5007112-801887 .		* 31/05/2026 01:16