



PSR | BSI Colombia S.A.

1/06/2026	95011484	DC00	24
1/06/2026	95011484	RC00	3

SUPERV JHON GUTIERREZ WTM-Vanti TRABAJO: 1/06/2026 TECNICO: 95011484 JHON SALINAS

MALLA SECTOR		SECC DIRECCION		CUENTA	ODS	ORDEN	MEDIDOR	DESCRIPCION AVISO	TOTAL: 27
179	NUTIBARA	008	CL 70H SUR 18P 41 00001	61193338	W 101332333	. DC00	CREA	5087195-69597	
179	NUTIBARA	008	CL 70M SUR 18P 28 00001	60782615	W 101355145	. DC00	CREA	5087195-68379	
179	NUTIBARA	008	CL 70M SUR 18P 28 02 00001	62066269	W 101355147	. DC00	CREA	5007108-421325	
179	NUTIBARA	008	KR 18N 70M SUR 5 01	61561379	W 101345601	. DC00	CREA	5087104-13403	
179	NUTIBARA	008	KR 18P 70M SUR 13	61582294	W 101355332	. DC00	CREA	5077101-1097608	
179	NUTIBARA	008	KR 18R 70H SUR 81 01	61989960	W 101356617	. DC00	CREA	5187101-273586	
179	NUTIBARA	008	TV 18N BIS 69R SUR 30 IBF	61713815	W 101358267	. DC00	CREA	5097106-224744	
179	NUTIBARA	009	CL 71B SUR 18Q 26 00001	61798160	W 41961011	. RC00	CREA	000005027191174536	* 31/05/2026 07:06
179	NUTIBARA	009	TV 19 73 SUR 52 00001	61036560	W 101356438	. DC00	CREA	5087195-69450	
179	VILLA FLOR	007	CL 70B SUR 20 97	61420362	W 101359019	. DC00	CREA	5057105-154626	
179	VILLA FLOR	013	CL 70L SUR 22 53 INT 00001	61725107	W 101312221	. DC00	CREA	5077101-1093892	
179	VILLA FLOR	013	KR 26 BIS 73B SUR 45 00001	62050659	W 101307827	. DC00	CREA	5107106-600009115	
179	VILLA FLOR	014	CL 70I SUR 26 38 01 00101	63320613	W 101308806	. DC00	CREA	5007119-3530930	
179	VILLA FLOR	014	CL 70I SUR 26 74 01 00101	63061037	W 101312731	. DC00	CREA	5017118-3508685	
179	VILLA FLOR	014	CL 70J SUR 26 80 00001	63743178	W 101313643	. DC00	CREA	007120210003792644	
179	VILLA FLOR	015	CL 72G SUR 26C 70	62482386	W 101281385	. DC00	CREA	007120210003781027	
179	VILLA FLOR	015	DG 73A SUR 27C 26	61385599	W 101283924	. DC00	CREA	5057105-88103	
179	VILLA FLOR	015	KR 27 72C SUR 46 CSA 01 00002	63465769	W 101291614	. DC00	CREA	007120200003659154	
179	VILLA FLOR	016	CL 73D BIS A SUR 26D 13 01 00001	62776544	W 101285155	. DC00	CREA	5007119-3584249	
179	VILLA FLOR	016	CL 74B SUR 27B 42 01 00101	63613301	W 101275492	. DC00	CREA	009520210000008959	
179	VILLA FLOR	016	KR 26G 72G SUR 11 02 00001	62941955	W 101291587	. DC00	CREA	5017118-3400638	
179	VILLA FLOR	016	KR 26G 72G SUR 34	62048117	W 101311829	. DC00	CREA	5007111-713487	
179	VILLA FLOR	016	KR 27 BIS A 73 SUR 58	61980481	W 41961068	. RC00	CREA	5107104-74272	* 31/05/2026 08:00
179	VILLA FLOR	017	DG 75B SUR 26C 35 I01 01 00003	63099348	W 101308723	. DC00	CREA	5007120-3638716	
179	VILLA FLOR	017	DG 75B SUR 26C 73	61883663	W 41962556	. RC00	CREA	5007114-967811	01/06/2026 05:12
179	VILLA FLOR	017	KR 26C BIS 75B SUR 76 01	62731872	W 101309576	. DC00	CREA	5017118-3416261	
179	VILLA FLOR	017	TV 26C BIS 75C SUR 65	62110952	W 101291519	. DC00	CREA	5007108-383524	