

Changelog

0.2

- change ferrules 1076990000 to MULTICOMP E7508-L-WHITE

Číslo revize: Datum vydáni:

PRUSA 8.1.2020 RESEARCH