

Incident Report — INC-2024-006

Near Miss | Medium Severity

Incident ID	INC-2024-006
Date	2024-04-15
Equipment Tag	200-V-210
Equipment Name	Low Pressure Separator
Unit	Hydrocracker Unit (200)
Type	Near Miss
Severity	Medium
Investigator	Ashok Joshi (HSE Officer, EMP-0035)
Regulatory Reportable	No
Follow-up Work Order	WO-2025-0013

1. Incident Summary

On 2024-04-15, a medium severity near miss was recorded on 200-V-210 (Low Pressure Separator) in the Hydrocracker Unit. The event was investigated by Ashok Joshi (HSE Officer, EMP-0035).

2. Root Cause

Investigation determined the probable root cause to be inadequate lockout-tagout verification prior to maintenance. Contributing factors were reviewed against the governing procedure SOP-200-004 and safety procedure SP-005.

3. Corrective Actions

A follow-up work order WO-2025-0013 was raised to address the immediate equipment condition. This event did not meet the threshold for external regulatory reporting.