

Incident Report — INC-2025-012

Relief Valve Lift | Medium Severity

Incident ID	INC-2025-012
Date	2025-10-04
Equipment Tag	100-PSV-110
Equipment Name	Column Relief Valve
Unit	Crude Distillation Unit (100)
Type	Relief Valve Lift
Severity	Medium
Investigator	Sunil Naik (HSE Officer, EMP-0034)
Regulatory Reportable	No
Follow-up Work Order	None issued

1. Incident Summary

On 2025-10-04, a medium severity relief valve lift was recorded on 100-PSV-110 (Column Relief Valve) in the Crude Distillation Unit. The event was investigated by Sunil Naik (HSE Officer, EMP-0034).

2. Root Cause

Investigation determined the probable root cause to be instrumentation drift causing delayed alarm response. Contributing factors were reviewed against the governing procedure SOP-100-002 and safety procedure SP-005.

3. Corrective Actions

No immediate corrective work order was required; findings were logged for trend monitoring. This event did not meet the threshold for external regulatory reporting.