

Incident Report — INC-2025-015

Process Upset | Critical Severity

Incident ID	INC-2025-015
Date	2025-08-21
Equipment Tag	300-P-305
Equipment Name	Boiler Feed Water Pump
Unit	Utilities & Offsites (300)
Type	Process Upset
Severity	Critical
Investigator	Rajesh Gaikwad (Reliability Engineer, EMP-0013)
Regulatory Reportable	No
Follow-up Work Order	None issued

1. Incident Summary

On 2025-08-21, a critical severity process upset was recorded on 300-P-305 (Boiler Feed Water Pump) in the Utilities & Offsites. The event was investigated by Rajesh Gaikwad (Reliability Engineer, EMP-0013).

2. Root Cause

Investigation determined the probable root cause to be process upset from upstream unit. Contributing factors were reviewed against the governing procedure SOP-300-009 and safety procedure SP-007.

3. Corrective Actions

No immediate corrective work order was required; findings were logged for trend monitoring. This event did not meet the threshold for external regulatory reporting.