

Inspection Report — 200-F-206

Internal (Vessel Entry) | 2024-06-23

Report ID	IR-200-F-206-2024-026
Equipment Tag	200-F-206
Equipment Name	Reactor Feed Heater
Unit	Hydrocracker Unit (200)
Inspection Date	2024-06-23
Inspection Type	Internal (Vessel Entry)
Inspector	Pooja Bhosale (Inspection Engineer, EMP-0017)
Next Due Date	2025-06-23
Governing SOP	SOP-200-006

1. Scope

Risk-Based Inspection (RBI) assessment of 200-F-206 performed by Pooja Bhosale (Inspection Engineer, EMP-0017) in accordance with SOP-200-006 and OISD inspection guidelines.

2. Findings

During Internal (Vessel Entry) inspection of 200-F-206 (Reactor Feed Heater) conducted on 2024-06-23, the inspector identified a minor severity defect: localized surface corrosion within allowable limits. This finding has been logged against the equipment's RBI history and a follow-up inspection is scheduled for 2025-06-23.

3. Recommendation

Recommend monitoring at next scheduled interval and update of the risk-based inspection interval for 200-F-206 accordingly.