

Inspection Report — 300-V-307

Internal (Vessel Entry) | 2026-02-10

Report ID	IR-300-V-307-2026-034
Equipment Tag	300-V-307
Equipment Name	Deaerator
Unit	Utilities & Offsites (300)
Inspection Date	2026-02-10
Inspection Type	Internal (Vessel Entry)
Inspector	Sunita Patil (Inspection Engineer, EMP-0015)
Next Due Date	2028-02-10
Governing SOP	SOP-300-009

1. Scope

Risk-Based Inspection (RBI) assessment of 300-V-307 performed by Sunita Patil (Inspection Engineer, EMP-0015) in accordance with SOP-300-009 and OISD inspection guidelines.

2. Findings

During Internal (Vessel Entry) inspection of 300-V-307 (Deaerator) conducted on 2026-02-10, the inspector identified a minor severity defect: slight external pitting, remedial coating recommended. This finding has been logged against the equipment's RBI history and a follow-up inspection is scheduled for 2028-02-10.

3. Recommendation

Recommend monitoring at next scheduled interval and update of the risk-based inspection interval for 300-V-307 accordingly.