

## Inspection Report — 400-T-404

Ultrasonic Thickness | 2024-09-13

|                 |                                               |
|-----------------|-----------------------------------------------|
| Report ID       | IR-400-T-404-2024-021                         |
| Equipment Tag   | 400-T-404                                     |
| Equipment Name  | LPG Bullet                                    |
| Unit            | Tank Farm / Storage (400)                     |
| Inspection Date | 2024-09-13                                    |
| Inspection Type | Ultrasonic Thickness                          |
| Inspector       | Pooja Bhosale (Inspection Engineer, EMP-0017) |
| Next Due Date   | 2025-03-12                                    |
| Governing SOP   | SOP-400-012                                   |

### 1. Scope

Risk-Based Inspection (RBI) assessment of 400-T-404 performed by Pooja Bhosale (Inspection Engineer, EMP-0017) in accordance with SOP-400-012 and OISD inspection guidelines.

### 2. Findings

Ultrasonic Thickness inspection of 400-T-404 (LPG Bullet) on 2024-09-13 found the equipment in satisfactory condition with no reportable defects. Readings are within acceptable limits per design basis.

### 3. Recommendation

Continue on standard RBI interval. Next inspection due 2025-03-12.