

Inspection Report — 500-AGT-501

Corrosion Mapping | 2026-07-10

Report ID	IR-500-AGT-501-2026-039
Equipment Tag	500-AGT-501
Equipment Name	Flocculation Agitator
Unit	Effluent Treatment Plant (500)
Inspection Date	2026-07-10
Inspection Type	Corrosion Mapping
Inspector	Sunita Patil (Inspection Engineer, EMP-0015)
Next Due Date	2027-01-06
Governing SOP	SOP-500-015

1. Scope

Risk-Based Inspection (RBI) assessment of 500-AGT-501 performed by Sunita Patil (Inspection Engineer, EMP-0015) in accordance with SOP-500-015 and OISD inspection guidelines.

2. Findings

During Corrosion Mapping inspection of 500-AGT-501 (Flocculation Agitator) conducted on 2026-07-10, the inspector identified a minor severity defect: slight external pitting, remedial coating recommended. This finding has been logged against the equipment's RBI history and a follow-up inspection is scheduled for 2027-01-06.

3. Recommendation

Recommend monitoring at next scheduled interval and update of the risk-based inspection interval for 500-AGT-501 accordingly.