

Maintenance Work Order — WO-2026-0009

Predictive | 300-V-307

Work Order ID	WO-2026-0009
Date	2026-02-28
Equipment Tag	300-V-307
Equipment Name	Deaerator
Unit	Utilities & Offsites (300)
Type	Predictive
Assigned To	Arun Patil (Electrical Engineer, EMP-0041)
Downtime (hrs)	8.2
Cost (INR)	406,126
Status	Closed
Linked Incident	None

1. Job Description

Predictive maintenance job on 300-V-307 (Deaerator): vibration analysis triggered bearing replacement. Work performed by Arun Patil (Electrical Engineer, EMP-0041).

2. Safety & Isolation

Work executed under isolation per SP-008 (Chemical Handling and Spill Response - ETP). Governing operating procedure: SOP-300-009.

3. Outcome

Equipment downtime of 8.2 hours recorded. Total job cost INR 406,126. Work order status: Closed.