

Maintenance Work Order — WO-2026-0046

Corrective | 200-P-208

Work Order ID	WO-2026-0046
Date	2026-01-09
Equipment Tag	200-P-208
Equipment Name	Product Pump
Unit	Hydrocracker Unit (200)
Type	Corrective
Assigned To	Arun Patil (Electrical Engineer, EMP-0041)
Downtime (hrs)	34.2
Cost (INR)	631,410
Status	Closed
Linked Incident	None

1. Job Description

Corrective maintenance job on 200-P-208 (Product Pump): mechanical seal replacement following observed leakage. Work performed by Arun Patil (Electrical Engineer, EMP-0041).

2. Safety & Isolation

Work executed under isolation per SP-003 (Confined Space Entry - Vessels and Tanks). Governing operating procedure: SOP-200-005.

3. Outcome

Equipment downtime of 34.2 hours recorded. Total job cost INR 631,410. Work order status: Closed.