

Incident Report — INC-2024-005

Minor Leak | Low Severity

Incident ID	INC-2024-005
Date	2024-08-03
Equipment Tag	500-P-505
Equipment Name	Sludge Recirculation Pump
Unit	Effluent Treatment Plant (500)
Type	Minor Leak
Severity	Low
Investigator	Sunil Naik (HSE Officer, EMP-0034)
Regulatory Reportable	No
Follow-up Work Order	None issued

1. Incident Summary

On 2024-08-03, a low severity minor leak was recorded on 500-P-505 (Sludge Recirculation Pump) in the Effluent Treatment Plant. The event was investigated by Sunil Naik (HSE Officer, EMP-0034).

2. Root Cause

Investigation determined the probable root cause to be inadequate lockout-tagout verification prior to maintenance. Contributing factors were reviewed against the governing procedure SOP-500-015 and safety procedure SP-002.

3. Corrective Actions

No immediate corrective work order was required; findings were logged for trend monitoring. This event did not meet the threshold for external regulatory reporting.